DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT				
Date of Maintenance	Maintenance:	5 Mark		
Property Address: 8519 A idae	in Bay Targerry	Owner's Name:	Tarion 0	we
Municipality: Lake Elmo State Zip Code SOV GEO Code/Property I.D. #:				
What was done to the system?	Tank Measu	rements (must be com	pleted if tanks NOT pumped)	
☐ Tank(s) Pumped ☐ Sludge and scum measured. Do tanks need to be pumped?	Liquid Level of Tank	in. Sludge Le		in.
☐ Yes ☐ No (If no provide measurements)	Total (Sludge + Scum)	/ Liquid Leve	= % Sludge & Scum	
1. Access used to remove septage: Maintenan	ce Hole	to #3 below)	* Tank must be pumped if the	is value
2. If maintenance hole was used, were all covers se	curely replaced?	No please expla	is greater than 25%.	
Explanation:				
3. If owner refuses to allow a Subsurface Sewage them complete and sign the following statem		STS) to be pumped th	rough the maintenance hole,	have
l, (owner's name), refuse to allow the removal of solids and liquids through the maintenance				
hole. I understand that removal of solids and liq				
4. Is the tank designed as a leaky tank? example: see	e <mark>page pit, c</mark> esspool, dryw	vell, leaching pit	$\overline{}$	
Tank#1 Yes Wo Verificatio Method Us	Pre	ai		
Tank#2 Yes No Verificatio Method Us	øđ:	-		
5. Is there evidence of tank leakage from a septi damaged, cracked, or structurally unsound m			w the operating depth or evid	dence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes TNO	T Yes No	☐ Yes ☐ No	**
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
6. How many gallons of septage were removed?	,			
Tank #1 / Tank #2 Pretreatment Tank		Pump Tank		
7. Other information: List any troubleshooting,	 minor repairs conduc	ted, tank safety conce	rns, or other concerns.	
		•		
8. Certification: I hereby certify as a State of Minr and made the observations, or di				
Maintainer's Name: SMILIE'S SEWER SERVICE	Maintainer's	Address: Scandia, MN		
Maintainer's License #: 2428 Maintaine	r's Phone #: _651-433-3			
Maintainer's Signature	1/2	Date:	2-11-13	