DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

n-71	SSTS MAINTEN	NCE REPORT			
Date of Maintenance	son for Maintenance:	PG MAIL	<u> </u>		
Property Address: 20703	remath proper	ty Owner's Name:	Reprette	o Whi	
Municipality: TOPE Lake	State Zip Code	5505 GEO CO	de/Property I.D. #:		
What was done to the system?	Tank Meas	Tank Measurements (must be completed if tanks NOT pumped)			
Tank(s) Pumped	 Liquid Level of Tank	Liquid Level of Tank in. Sludge Level in. Scum Level in			
Sludge and scum measured. Do tanks need to be pumped?	.	*			
Yes No (If no provide measure	ements) Total (Sludge + Scu) Liquid Lev	el = % Sludge & Scu	ım	
1. Access used to remove septage: Ma		io to #3 below)	* Tank must be pumped if is greater than 25%.	this value	
2. If maintenance hole was used, were all o	overs securely replaced?	Yes ☐ No please expl			
Explanation:					
3. If owner refuses to allow a Subsurface them complete and sign the following		(SSTS) to be pumped t	hrough the maintenance ho	le, have	
I, hole. I understand that removal of solid			ds and liquids through the mai lered maintenance.	intenance	
4. Is the tank designed as a leaky tank? exc)		
Tank#1 Yes No Verificatio M	ethod Used:	Casi			
Tank#2 Yes No Verificatio M	/ ethod Used:				
5. Is there evidence of tank leakage from damaged, cracked, or structurally uns	n a septic, holding, pretreat	ment or pump tank bel	ow the operating depth or e	vidence of	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	Yes No	Yes TNo	Yes TNO		
Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	┌ Yes ┌ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No		
Pump Tank	☐ Yes ☐ No	Yes No	Yes No		
6. How many gallons of septage were re	emoved?				
Tank #1 / 00 Tank #2	Pretreatment Ta	nk P	ump Tank		
7. Other information: List any troubles	nooting, minor repairs cond	ucted, tank safety conc	erns, or other concerns.		
<u> </u>					
8. Certification: I hereby certify as a Stat and made the observation	e of Minnesota certified SSTS ons, or directly supervised ot	Maintainer that I person ners in the performance	ally conducted the work of this job.		
Maintainer's Name: SMILIE'S SEWER SE	RVICE Maintain	er's Address: Scandia, Mi	4		
Maintainer's License #: 2428	Maintainer's Phone #: 651-43	3-3005	> 2/		
Maintainer's Signature	End of	Date:			