## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

**SSTS MAINTENANCE REPORT** 

Date of Maintenance 12-2-13 Reason for	Maintenance:	en Mast		
Property Address: 15857 Forces	T Blud Noper	ty Owner's Name: $\frac{1}{100}$	Austrial Utili	Z
Municipality: Hugo 5	tate////Zip Code	55036 GEO Code/	Property I.D. #:	
What was done to the system?	Tank Measurements (must be completed if tanks NOT pumped)			
Tank(s) Pumped Sludge and scum measured. Do tanks need to be pumped?	Liquid Level of Tank	<del></del>	in. Scum Level in = % Sludge & Scum	. *
Yes No (If no provide measurements)	Total (Siddye + Std			
1. Access used to remove septage: Maintenar		io to #3 below)	<ul> <li>Tank must be pumped if this valu is greater than 25%.</li> </ul>	e
2. If maintenance hole was used, were all covers se	ecurely replaced?	Yes No please explain		
Explanation:				
3. If owner refuses to allow a Subsurface Sewag them complete and sign the following statem		(SSTS) to be pumped thro	ugh the maintenance hole, have	_
		· ·	nd liquids through the maintenanc	:e
hole. I understand that removal of solids and lic			ed maintenance.	
<b>4.</b> Is the tank designed as a leaky tank? <i>example: se</i>	epage pit, cesspool, dr	ywell, leaching <u>pit</u>		
Tank#1 Yes Verificatio Method U	sed: DrC	casi.	•	
Tank#2 Tyes No Verificatio Method U	sed:		n	
5. Is there evidence of tank leakage from a sept	<u></u>	ment or numn tank helow	the operating depth or evidence	
damaged, cracked, or structurally unsound n	<del>-</del> -		the operating acpen of criacine	Ų.
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank#1	Yes No	Yes Z No	Yes Avo	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
6. How many gallons of septage were removed	?			
Tank #1	Pretreatment Ta	nk Pum	p Tank	
7. Other information: List any troubleshooting,	minor repairs cond	ıcted, tank safety concern	s, or other concerns.	
4				
		*		
<b>8. Certification:</b> I hereby certify as a State of Min and made the observations, or o				
	lirectly supervised oth			
and made the observations, or of Maintainer's Name: SMILIE'S SEWER SERVICE	lirectly supervised oth	er's Address: Scandia, MN		