

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance Property Address:	12580 182 nd St	for Maintenance: _	Property Owner's N	ame: Rolf B	roun	
Municipality:		Property Idea				
Maintenance Permit	No: p 0992 122094	Maintainer Name ar	nd License No. Smil	ie's Sewer Service/L	2428	
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
<ul> <li>▼ Tank(s) Pumped</li> <li>□ Sludge and scum measured</li> <li>□ Do tanks need to be pumped?</li> <li>□ Yes □ No (if no provide measurements)</li> </ul>		Sludge Level in Sludge + Scum _ = % Sludge & Sci	Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater			
	T 0 : 4	ance Hole Other	enter authorization c	ode)		
2. Were all covers s 3. Is there evidence	emove septage:   Mainten  Mecurely replaced?   Yes  Me of tank leakage from a se  Maged, cracked, or structu	□ No eptic, holding, pret	reatment or pump	tank below the ope	erating depth or	
2. Were all covers s 3. Is there evidence	ecurely replaced? 🎾 Yes of tank leakage from a se	□ No eptic, holding, pret	reatment or pump	tank below the ope	erating depth or	
2. Were all covers s 3. Is there evidence	ecurely replaced? Yes of tank leakage from a se naged, cracked, or structu	No Poptic, holding, pretigrally unsound main	reatment or pump itenance hole cove	tank below the ope ers? 🗌 Yes 岚 No	erating depth or	
2. Were all covers s 3. Is there evidence	ecurely replaced? Yes of tank leakage from a se naged, cracked, or structu Tank	No Peptic, holding, pretigrally unsound main Leaking Out	reatment or pump itenance hole cove Leaking In	tank below the ope ers? Yes No Cover Damage	erating depth or	
2. Were all covers s 3. Is there evidence	recurely replaced? Yes of tank leakage from a se naged, cracked, or structu  Tank  Septic/Holding Tank #1	No eptic, holding, pretigrally unsound main Leaking Out	reatment or pump stenance hole cove  Leaking In  Yes ANO	tank below the operers?  Yes No  Cover Damage  Yes No	erating depth or	
2. Were all covers s 3. Is there evidence	recurely replaced? Yes e of tank leakage from a se naged, cracked, or structu  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2	No Peptic, holding, pretigrally unsound main  Leaking Out  Yes No  Yes No	Leaking In  Yes No	tank below the operers?	erating depth or	

Smilie's Sewer Service PO BOX 100 Scandia, MN 55073 License# 2428 P: 651-433-3934