R See C See W See For

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

JAN 05 2016

CCTC MAINTENANCE REDORT

16 18 16	SIS MAIIVIENA	MCE REPORT		
Date of Maintenance /// AT/ Perason for	or Maintenance:	s/larg/		/
Property Address: 20491 057	NUM Ave Property	/ Owner's Name:	chard Hud	500
Municipality: Maryne	State Zip Code	3504 GEO Code	e/Property I.D. #:	
What was done to the system?	Tank Measu	Tank Measurements (must be completed if tanks NOT pumped)		
Tank(s) Pumped Sludge and scum measured.	Liquid Level of Tank in. Sludge Level in. Scum Level in.			
Do tanks need to be pumped? Yes No (If no provide measurement)	Total (Sludge + Scun	n)/ Liquid Level	= % Sludge & Scum	*
1. Access used to remove septage: Mainter	nance Hole Other (Go	to #3 beløw)	* Tank must be pumped if this is greater than 25%.	value
2. If maintenance hole was used, were all covers	securely replaced?	res No please explai	-	
Explanation:				
3. If owner refuses to allow a Subsurface Sew them complete and sign the following state	-	SSTS) to be pumped thi	rough the maintenance hole, l	have
l, (or	wner's name), refuse to al	low the removal of solids	and liquids through the mainte	enance
hole. I understand that removal of solids and	liquids through other acc	ess points is not conside	red maintenance.	
4. Is the tank designed as a leaky tank? example.	: seepage pit, cesspool, dry	well, leaching pit	-	
Tank#1 Yes No Verificatio Method	Used:	e Co		
Tank#2 Yes No Verificatio Method	Used:		,	
5. Is there evidence of tank leakage from a se damaged, cracked, or structurally unsound			w the operating depth or evid	ence of
Tank	Leaking Out	Leaking In	- Cover Damage	
Septic/Holding Tank #1	Yes THO	Yes TWO	Yes ZNO	
Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
6. How many gailons of septage were remov	ed?			
Tank #1 / / / Tank #2	Pretreatment Tan	ıkPur	mp Tank	
7. Other information: List any troubleshootis	ng, minor repairs condu	cted, tank safety concer	ns, or other concerns.	
8. Certification: I hereby certify as a State of M and made the observations, c				
Maintainer's Name: SMILIE'S SEWER SERVICE	Maintaine	r's Address: Scandia, MN		
Maintainer's License #: 2428 Mainta	iner's Phone #: 651-433			
Maintainer's Signature	ail H	Date:	1-18-15	