DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT w2931x 21489

Date of Maintenance 4/8/21 Reason	on for Maintenance:	Compliance		
Property Address: 20540 St.C.			Peter Ostrand	
Municipality: Scandia	State MV Zip Cod	de <u>55073</u> GEO	Code/Property I.D. #:	
What was done to the system?	Tank Me	asurements (must be	completed if tanks NOT pumped)	
☐ Sludge and scum measured. Do tanks need to be pumped? ☐ Yes ☐ No (If no provide measurem)	Liquid Level of Ta			in.
1. Access used to remove septage: Maint		(Go to #2 holow)	* Tank must be pumped if this v	/alue
2. If maintenance hole was used, were all covered to the second of the s			is greater than 25%	-,
Explanation:	recurely replaced: A	Tiles [] No pieuse e.	<i>kpiain</i>	
3. If owner refuses to allow a Subsurface Sethem complete and sign the following state. I, hole. I understand that removal of solids are 4. Is the tank designed as a leaky tank? examp Tank#1 Yes You Verificatio Method	owner's name), refuse to d liquids through other le: seepage pit, cesspool, o	allow the removal of so access points is not con Irywell, leaching pit	olids and liquids through the maintena	
Tank#2 Yes No Verificatio Metho	Toloce	1 Tank		
5. Is there evidence of tank leakage from a		turant au mumo tonle le	alough and the	
damaged, cracked, or structurally unsour	nd maintenance hole co	rment or pump tank b vers?	elow the operating depth or eviden	ce of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes Alo	Yes No	Yes NiNo	
Septic/Holding Tank #2	☐ Yes ☐ No	Yes No	Yes No	
Pretreatment Tank	Yes No	☐ Yes ☐ No	Yes No	
Pump Tank	Yes No	Yes No	Yes No	
6. How many gallons of septage were remov	/ed?			
Tank #1 1200 Tank #2 Pretreatment Tank			Pump Tank	
7. Other information: List any troubleshooti	ng, minor repairs cond	ucted, tank safety con	cerns, or other concerns.	
B. Certification: I hereby certify as a State of Mande the observations, of	or directly supervised oth	Maintainer that I persor ners in the performance	nally conducted the work of this job.	
Maintainer's Name: Olson's Sewer Service, I	nc. Maintaine	r's Address: 17638 Lyo	ns Street NE, Forest Lake, MN	
Maintainer's License #: 216 Mainta	iner's Phone #: 651-46	1-2082		
Maintainer's Signature	2	Date: 🗷	4/09/7021	
			-y white-	