

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

					nance remine	
This section must	be completed in its entiret	y to constitute a	alid maintenance	permit. This permit	must be complete	
prior to per	iorning maintenance activ	ities and remain o	n-site for the dura	ation of the mainten	must be complete	
Date of Maintenance	e: 3-11-21 Reason	n for Maintenance	Prostrine	and of the maniteme	ince activity.	
Property Address: \(\)	1100 sasmine	TOI MU	Property Owner's	Name: Dennis	Lueck	
Municipality: SM	Muchor ZIP:55	OST Droparty Id	operty owner 3	rame. oci milo	- secre	
Maintonance Descrit	11 1791 mzs	28 Property Id	entification Numbe	r:		
Maintenance Permit	No: 1729 W 22235	Maintainer Name	and License No. Pin	ky's Environmental Se	ewer Service/ L167	
	The same of the sa		THE STATE OF THE S			
Maintenance Performed		The second secon	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		III	Liquid Level of Tank ——— in			
□ Sludge and scum measuredDo tanks need to be pumped?□ Yes □ No (if no provide measurements)			Sludge Level in Tank in Scum Level in Tank in			
		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
			= % Sludge & Scum Tanks must be pumped if 25% or greater			
. Access used to re	emove septage: Maintena	ince Hole 🗹 Other (enter authorization c	code) Janks in	- Elswor grid	
. Were all covers s	ecurely replaced? Yes	□No				
3. Is there evidence	of tank leakage from a sep	otic, holding, pret	reatment or numn	tank balanith		
evidence of dam	aged, cracked, or structur	ally unsound mair	itenance hole cove	ers? Vos No	ating depth or	
			- Total cove	ers: - 162 - 140		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
. How many gallons	of septage were removed?					
Tank #1 <u> </u>	gal Tank #2 / Joo	gal Pretreatment	tank	-		
. Other information	: List any troubleshooting,	minor ropairs so	dust du l	at Pump Tank	gal	
	, a cableshooting,	millor repairs cor	iducted, tank safe	ty concerns, or other	concerns.	
Location of septage	e disposal:					
	Dint. 1					
	rinky's	Environmental Se				
		PO Box 35	4			

P: 651-439-4847 License Number: L1673

Afton MN 55001