DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintena	nce 10-30-15 Reason for	Maintenance: Zov	Love		
Property Address:	: 8841 Lake Jan	u h Ma Property	Owner's Name:	usel miller	
Municipality:	, ,	State /11 Zip Code			
What wa	s done to the system?	Tank Measu	rements (must be com	pleted if tanks NOT pumped)	
☐ Tank(s) Pumped ☐ Sludge and scum measured. ☐ Do tanks need to be pumped? ☐ Yes ☐ No (If no provide measurements		Liquid Level of Tank in. Sludge Level in. Scum Level in. Total (Sludge + Scum) / Liquid Level = % Sludge & Scum *			
	remove septage: Maintena		to #3 below)	* Tank must be pumped if this value	ıe -
	hole was used, were all covers s			is greater than 25%. nin	
		ti work -	Ference vi		
Explanation:	os to allow a Subsurface Sowa	no Treatment System /	SSTS) to be numbed th	nrough the maintenance hole, have	
	es to allow a Substitute Sewa e and sign the following state		3313, to be painped to	mough the manifement note, nove	•
l,	(ow	ner's name), refuse to all	ow the removal of solid	s and liquids through the maintenan	ce
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.					
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit					
Tank#1 🔲 Ye	s TWO Verificatio Method U	Jsed:			
Tank#2 □ Ye	s No Verificatio Method U	Jsed:			
tummi	Name of the state		nent or pump tank belo	ow the operating depth or evidence	 e of
	ked, or structurally unsound				
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No	☐ Yes ☐ No	Yes Lino	
	Septic/Holding Tank #2	Yes No	Yes LNO	Yes No	
	Pretreatment Tank	Yes No	Yes No	Yes No	
	Pump Tank	Yes No	☐ Yes ☐ No	Yes No	
6. How many gal	llons of septage were remove	d?			
Tank #1 /Occo Tank #2 /Ocoo Pretreatment Tank Pump Tank					
7. Other informa	ation: List any troubleshooting	g, minor repairs condu	cted, tank safety conce	erns, or other concerns.	
	•	-			
8. Certification:	I hereby certify as a State of Mi and made the observations, or	nnesota certified SSTS M directly supervised othe	laintainer that I persona ers in the performance o	lly conducted the work of this job.	•
Maintainer's N	ame: PINKY'S SEWER SERVICE	Maintainer	's Address: P.O. Box 354	Afton, MN 55001	
Maintainer's Li	icense #: 1673 Maintai	ner's Phone #: 651-439	-4847 		
Maintainer's Si	ignature The A (Pour	Date: /	5-30-15	