DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintena	ince 10-14-17 Reason fo	r Maintenance:	outine_		
Property Address	13600 44 St C	t N Property	Owner's Name: 50	nn Rozni	CK
Municipality:	fillunter	State M Zip Code .	GEO Code	e/Property I.D. #:	
What w	as done to the system?	Tank Measu	rements (must be com	pleted if tanks NOT pumpe	(d)
 ☐ Tank(s) Pumped ☐ Sludge and scum measured. Do tanks need to be pumped? ☐ Yes ☐ No (If no provide measurements) 		Liquid Level of Tank	Liquid Level of Tank in. Sludge Level in. Scum Level		
		Total (Sludge + Scum	n) / Liquid Leve	= % Sludge & Scu	.m*
	remove septage: • Maintena		to #3 below)	* Tank must be pumped if	this value
	hole was used, were all covers			is greater than 25%. in	
		Toward .	Fromered #		
Explanation:	es to allow a Subsurface Sewa	na Treatment System	SSTS) to be pumped th	rough the maintenance ho	
them complet	e and sign the following state	ment:	33137 to be pumped an		
l,	(ow	ner's name), refuse to al	low the removal of solids	s and liquids through the ma	aintenance
hole. I underst	and that removal of solids and l	iquids through other acc	cess points is not conside	ered maintenance.	
4. Is the tank des	igned as a leaky tank? example:	seepage pit, cesspool, dry	well, leaching pit		
Tank#1 🔽 Ye	es TNo Verificatio Method	Used:			
Summer	Kaume				
Tank#2 Tank#2	Saural	 .	4 4 4 1 1		ovidonso of
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
,	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No	Yes No	[Yes [UNo	
	Septic/Holding Tank #2	Yes No	Yes No	☐ Yes ☐ No	
	Pretreatment Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	Yes No	☐ Yes ☐ No	Yes No	
6. How many ga	allons of septage were remove	d?			
Tank #1 /5	OO Tank#2	Pretreatment Tank Pum		mp Tank	
7. Other inform	ation: List any troubleshootin	g, minor repairs condu	cted, tank safety conce	rns, or other concerns.	
	•				
8. Certification:	: I hereby certify as a State of M and made the observations, o	innesota certified SSTS Ardirectly supervised oth	Naintainer that I persona ers in the performance o	lly conducted the work f this job.	
Maintainer's N	Name: PINKY'S SEWER SERVICE	Maintaine	r's Address: P.O. Box 354	Afton, MN 55001	
Maintainer's l		ner's Phone #: 651-439	-4847		
Maintainer's S	Signature 7/10	Olivas	Date: //	3-14-15	