

Soil Observation Log

Project ID:

v 04.01.2020

Client: Joe Roybal **Location / Address:** 4720 Wild Canyon Drive

Soil parent material(s): (Check all that apply) Outwash Lacustrine Loess Till Alluvium Bedrock Organic Matter

Landscape Position: (select one) **Slope shape:** **Elevation-relative to benchmark:**

Vegetation: Lawn **Soil survey map units:** **Limiting Layer Elevation:**

Weather Conditions/Time of Day: 55 degrees 4:00 **Date:** 04/13/21

Observation #/Location: 2' from STA **By Line #1** **Observation Type:** Auger

Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Structure	
							Shape	Grade
0-24"	Loam	<35%	7.5YR 4/3					
24 - 50"	Loamy Sand	<35%	10YR 4/6					
50 - 60"	Sand	<35%	7.5YR 4/4					

I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.

S. Schlomka L4137P 4/13/2021
 (Designer/Inspector) (License #) (Date)

Optional Verification: I hereby certify that this soil observation was verified according to Minn. R. 7082.0500 subp. 3 A. The signature below represents an infield verification of the periodically saturated soil or bedrock at the proposed soil treatment and dispersal site.

 (LGU Inspector) _____ _____
 (Signature) (Cert. #) (Date)