

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to performing	g maintenance activitie	s and remain on-	site for the duratio	n of the maintenand	ce activity.
Date of Maintenance: 5^{-1}	27-16 Reason fo	or Maintenance: _	Cleaning		
Property Address: 1466	1 185th St 1	/ Pi	operty Owner's Na	me: James	Moore
Municipality: Marine of	St. CroixZIP: 550L	Property Iden	tification Number:		
Maintenance Permit No:(0.00			428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
Yes No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to remove septage: Maintenance Hole Other (enter authorization code) Mo Men way access Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 					
	Tank	Leaking Out	Leaking In	Cover Damage	
Sep	tic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Sep	otic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pro	treatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
rie	de catherie rank	□ 163 □ 110	□ 162 □ 140		
	mp Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	mp Tank				
4. How many gallons of s	mp Tank eptage were removed?	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	gal
4. How many gallons of s	mp Tank eptage were removed? al Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No al Pump Tank	