DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 4/20/2	Reason for A	Maintenance:	~ 4279e	22341	0		
Property Address: 22740K	rik Av.	Pro	operty Owner's	Name:			
Municipality: Scandia	Sta	ite Zip C	ode	GEO Cod	e/Property I.D.	#:	
What was done to the sy	stem?	Tank N	leasurements	(must be com	pleted if tank	s NOT pumped)	
Tank(s) Pumped						1	AND SECTION ASSESSMENT
Sludge and scum measured.	- 11	Liquid Level of		in. Sludge Le	vel in.	Scum Level	in.
Do tanks need to be pumped?	1	Total (Sludge +	Scum)	Liquid Level	04	Shades & Carre	
Yes No (If no provide	neasurements)	Total (Sluage T		Liquid Leve	= 70	Sludge & Scum ——	
1. Access used to remove septage:					is greater th	be pumped if this va nan 25%.	alue
2. If maintenance hole was used, we	ere all covers secu	urely replaced?	Yes No	please explai	n		
Explanation:							
3. If owner refuses to allow a Substhem complete and sign the fol	surface Sewage ' lowing stateme	Treatment Syst	em (SSTS) to be	e pumped thr	ough the mai	ntenance hole, ha	
l,	(owner	s name), refuse	to allow the rem	noval of solids	and liquids thr	ough the maintena	nce
hole. I understand that removal c	f solids and liqui	ds through othe	r access points i	s not consider	ed maintenanc	e.	100
4. Is the tank designed as a leaky tar							
Tank#1 Yes No Verifica	ntio Method Used	1: Pumped	Tank				
Tank#2 Yes No Verifica	itio Method Used	l:					
					4		
Is there evidence of tank leakag damaged, cracked, or structural	ly unsound mai:	noiding, pretre ntenance hole c	eatment or pun covers?	ip tank below	the operating	j depth or evidenc	e of
Tank	L	eaking Out	Leakin	ng In	Cover Dama	ige	
Septic/Holding Ta	nk #1	Yes No	T Yes	No	Yes 🔃		
Septic/Holding Ta		Yes No	Yes				
Pretreatment Tank		Yes No		No	Yes []		
Pump Tank		Yes No	Yes		Yes [1		
		ies EZIAO		- IIAO	☐ Yes ☐	10	
6. How many gallons of septage was Tank #1 1750 Tank #2	ere removea?	Pretreatment 7	^r ank	Dumi	Tank 55	7/	
					1		
7. Other information: List any trou	bleshooting, mi	nor repairs con	ducted, tank sa	efety concern	s, or other con	cerns.	
8. Certification: I hereby certify as a and made the obse	State of Minnesorvations, or direc	ota certified SSTS tly supervised o	S Maintainer tha thers in the perf	nt I personally of the	conducted the is job.	work	_
Maintainer's Name: Olson's Sewe	Service, Inc.	Maintair	ner's Address: 1	7638 Lyons Sti	reet NE, Forest	Lake, MN	
Maintainer's License #: 216	Maintainer's F	Phone #: 651-4	64-2082				
Maintainer's Signature	7-11			Date: 4/0	1505/02/		
					,		