

## 520 Lafayette Road North St. Paul, MN 55155-4194

## Compliance inspection report form

## **Existing Subsurface Sewage Treatment System (SSTS)**

Doc Type: Compliance and Enforcement

**Instructions:** Inspection results based on Minnesota Pollution Control Agency (MPCA) requirements and attached supporting documentation – additional local requirements may also apply. Further information can be found here: <a href="https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf">https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf</a>.

Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance.

Property information	Local tracking number:
Parcel ID# or Sec/Twp/Range: 0803021320012 Local regulatory authority: Washington	
Property address: 10455 Hadley Cricle North	
Owner/representative: John & Angly Ulschmid	Owner's phone: 612-720-7061
Brief system description: Replacement system installed 2008 after	er other system failed
System status	
System status on date (mm/dd/yyyy): 4/21/2021	
○ Compliant – Certificate of compliance*	☐ Noncompliant – Notice of noncompliance
(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists	An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance or under section 145A.04 subdivision 8.
in Local Ordinance.) *Note: Compliance indicates conformance with Minn. R. 7080.1500 as of system status date above and does not guarantee future performance.	Systems failing to protect ground water must be upgraded, replaced, or use discontinued within the time required by local ordinance.
☐ Soil separation (Compliance component #5) – Failing	at #3) – Imminent threat to public health and safety at #3) – Failing to protect groundwater 500 (Compliance component #3) – Failing to protect groundwater
Certification	
abuse of the system, inadequate maintenance, or future water usage	nade due to unknown conditions during system construction, possible ge.
By typing my name below, I certify the above statements to be to can be used for the purpose of processing this form.	ue and correct, to the best of my knowledge, and that this information
Business name: SS Septic Solutions. LLC	Certification number: C9917
Inspector signature:	License number: L4137
(This document has been electronically signed)	Phone: 651-343-9117
Necessary or locally required supporting doc	
☐ Soil observation logs ☐ Locally required forms ☐ Other information (list):	☐ Tank Integrity Assessment ☐ Operating Permit