

POST - CONSTRUCTION INSPECTION

DATE 01/08/1986 TIME 1:46 AM
 PM INSPECTOR PAFF

REMARKS ONE INSPECTION RISER ON SEPTIC TANK. THREE INSPECTION RISER ON
DROP BOXES + THREE INSPECTION RISERS AT THE END OF FIELD.

95% COMPLETION.

HOME SEWER CONNECTION LENGTH IS: 10'
ELECTRICAL CONNECTION LENGTH: 160'
CONDUIT LENGTH: - 20'

SUBSTANTIAL COMPLETION OF SYSTEM _____
 INSPECTOR _____ DATE _____

DEFICIENCIES 1: FINAL GRADE NEED IMPROVEMENT. -5% (X) (D)
2: CUT INSPECTION RISERS TO (GROUND) LEVEL (X) (D)
3: SEED AND MULCH ARE $\geq 10\%$ SLOPE OVER TANKS & PRESSURE SEWER LINE.
(Slope southeast of house: seed not yet established) OK 5-29-87 R.T.

REQUIRED ACTION 4. Remove drainfield flood from neighbor's property. OK 5-29-87 R.T.

7/19/87 No state electrical inspection sticker 5-29-87 R.T.
7/30/87 Electrical inspection passed 7/22/87.

DATE CORRECTED 5-29-87 [Signature]
 INSPECTOR _____

100% complete

01/09/87 PUMP READINGS 7.2"

PHOTOGRAPHS 2 NUMBER TAKEN
20-21 SEQUENCE