DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 4/27 Reas	on for Maintenance:	+1704-2	2347	
Property Address: 20101 Hams	mp(RV.YV). Pro	perty Owner's Name:	Roger d Virginia	Rudolph
Municipality: Trustday		de 55025 GEO		λ.
What was done to the system?	Tank M	easurements (must be c	ompleted if tanks NOT pun	nped)
Tank(s) Pumped				I server
Sludge and scum measured.	Liquid Level of Ta	ank in. Sludge	Level in. Scum Lev	rel in.
Do tanks need to be pumped? Yes No (If no provide measurem	Total (Sludge + Scum) / Liquid Level = % Sludge & Scum			
	ents)			
1. Access used to remove septage: Main			 Tank must be pumped is greater than 25%. 	d if this value
2. If maintenance hole was used, were all cov	ers securely replaced?	X Yes No please exp	plain	
Explanation:	,	,		
3. If owner refuses to allow a Subsurface So them complete and sign the following st	ewage Treatment Syste atement:	m (SSTS) to be pumped	through the maintenance	hole, have
•		a allamada a como control de la		
hole. I understand that removal of solids ar	towner's name), reruse to ad liquids through other	allow the removal of sol	ids and liquids through the r	naintenance
4. Is the tank designed as a leaky tank? examp			dered maintenance.	
		arywen, reacring pit		
Tank#1 Yes No Verificatio Metho	od Used: 			
Tank#2 Yes No Verificatio Metho	od Used:			
5. Is there evidence of tank leakage from a	septic, holding, pretrea	tment or pump tank be	low the operating depth of	r evidence of
damaged, cracked, or structurally unsou	nd maintenance hole co	overs?		Evidence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes 📈 No	Yes No	Yes No	-
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	÷
Pump Tank	☐ Yes ☐ No	Yes No	Yes No	ł
5. How many galions of septage were remov	ved?			ř
Tank#1 1250 Tank#2	Pretreatment Ta	enk Pe	ump Tank	
7. Other information: List any troubleshooti	ing, minor repairs cond	ucted, tank safety conc	erns, or other concerns.	
Contillant				
3. Certification: I hereby certify as a State of N and made the observations,	Vinnesota certified SSTS or directly supervised ot	Maintainer that I persona hers in the performance o	lly conducted the work f this job.	
Maintainer's Name: Olson's Sewer Service, I			Street NE, Forest Lake, MN	
Maintainer's License #: 216 Mainta	 ainer's Phone #: 651-46	4-2082		
Maintainer's Signature	71	Date: U	-22-21	
			20-41	