

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	4-19-21 Reason	for Maintenance:	Cleaning		
	357 117th St			ame: Mark & B	enda William
Municipality:5+r	Clarater ZIP: 550	57 Property Ide	ntification Number:		
	0: W1201422104A				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped  Sludge and scum measured Do tanks need to be pumped?  Yes No (if no provide measurements)		Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage:   Maintena	nce Hole Other	enter authorization co	ode) he minu	ey access
	of tank leakage from a sep ged, cracked, or structure Tank				rating depth or
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ☐ No	☐ Yes ☐No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	- '
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1_1259	of septage were removed gal Tank #2 List any troubleshooting,	gal Pretreatmen			

Smilie's Sewer Service **PO BOX 100** Scandia, MN 55073

License# 2428 P: 651-433-3934