DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenar	nce 10 1-15 Reason for	Maintenance: RO	tive		
Property Address:	2420 Overlook	Ct. No. Property	Owner's Name: Ret	er Melges	
		State <u>U</u> Zip Code _	55562 GEO Code	/Property I.D. #:	
, What wa	s done to the system?	Tank Measu	rements (must be comp	leted if tanks NOT pumped)
Tank(s) Pumpe	ed	Liquid Level of Tank	in. Sludge Lev	rel in. Scum Level	in.
Sludge and sc		Liquid Level of Tarik		<u> </u>	
	I to be pumped?	Total (Sludge + Scum) / Liquid Level	= % Sludge & Scun	
	No (If no provide measurements			* Tank must be pumped if the	nis value
1. Access used to	remove septage: Maintena	ince Hole Uther (Go	to #3 below)	is greater than 25%.	
2. If maintenance	hole was used, were all covers	securely replaced?	es No please explai	n	
Explanation:					
3. If owner refuse them complete	es to allow a Subsurface Sewa e and sign the following state	ge Treatment System (ment:	SSTS) to be pumped th	rough the maintenance hole	, have
1,				and liquids through the mair	ntenance
hole. I understa	and that removal of solids and I	iquids through other acc	ess points is not conside	red maintenance.	
4. Is the tank desi	gned as a leaky tank? example:	seepage pit, cesspool, dry	vell, leaching pit		
Tank#1 TYe	s No Verificatio Method	Used:			
	National Property and Control of the				
f	es No Verificatio Method			w the energting depth or ex	vidence o
5. Is there evide	nce of tank leakage from a se cked, or structurally unsound	ptic, holding, pretreath maintenance hole cove	ers?	w the operating departor of	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
damayed, crac	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	T Yes No	Yes L No	Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	Yes No	Yes No	
•	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	
	Pump Tank	Yes No	☐ Yes ☐ No	Yes No	
6. How many ga	illons of septage were remove	ed?			
<i>*</i>	7 Tank #2	Pretreatment Tar	ık Pı	mp Tank	•
Tank #1/ <u>C</u>	_ 	<u> </u>			
7. Other inform	ation: List any troubleshootir	ıg, minor repairs condu	cted, tank safety conce	rns, or other concerns.	
8. Certification:	I hereby certify as a State of M and made the observations, c	r directly supervised oth	ers in the performance o	this job.	
Maintainer's N		** * * * * * * * * * * * * * * * * * * *	r's Address: P.O. Box 354	Afton, MN 55001	
Mairitainer 5 i	Name: PINKY'S SEWER SERVICE	Maintaine	r's Address:		
		iner's Phone #: 651-439			