

Compliance inspection report form

Existing Subsurface Sewage Treatment System (SSTS) 520 Lafayette Road North St. Paul, MN 55155-4194

Doc Type: Compliance and Enforcement

Instructions: Inspection results based on Minnesota Pollution Control Agency (MPCA) requirements and attached supporting documentation - additional local requirements may also apply. Further information can be found here: https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf.

Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance.

Property information	Local tracking number:	
Parcel ID# or Sec/Twp/Range: Loc	cal regulatory authority:	
Property address: 15505 215th Street N, Scandia MN		
Owner/representative: Paul Gifford	Owner's phone: 651-433-3436	
Brief system description: 1250 main tank to inground gravity fed t	trenches	
System status		
System status on date (mm/dd/yyyy): 4/28/2021		
☐ Compliant – Certificate of compliance*	Noncompliant − Notice of noncompliance	
(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists in Local Ordinance.)	An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance or under section 145A.04 subdivision 8.	
*Note: Compliance indicates conformance with Minn. R. 7080.1500 as of system status date above and does not guarantee future performance.	Systems failing to protect ground water must be upgraded, replaced, or use discontinued within the time required by local ordinance.	
Reason(s) for noncompliance (check all applicable	e)	
Soil separation (Compliance component #5) – Failing	o protect groundwater nt #3) – Imminent threat to public health and safety nt #3) – Failing to protect groundwater 500 (Compliance component #3) – Failing to protect groundwater	
Certification		
abuse of the system, inadequate maintenance, or future water usa	made due to unknown conditions during system construction, possible	
Business name: MJL Contracting Inc.	Certification number: 8190	
Inspector signature: Danielle Lang	License number: 2449	
(This document has been electronically signed)	Phone: 763-244-9070	
Necessary or locally required supporting doc	umentation (must be attached)	
☑ Soil observation logs☑ Locally required forms☐ Other information (list):	☐ Operating Permit ☐ Operating Permit	

1. Impact on public health – Compliance component #1 of 5 | Compliance criteria: | Attached supporting documentation: | | System discharges sewage to the ground surface | Yes* ⋈ No | Other: | Not applicable | | System discharges sewage to drain tile or surface waters. | Yes* ⋈ No | Yes* ⋈ No | Any "yes" answer above indicates the system is an |

imminent threat to public health and safety. Describe verification methods and results:

Searched for seepage in yard

2. Tank integrity – Compliance component #2 of 5

Compliance criteria:		Attached supporting documentation:			
System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes* ⊠ No	□ Pumped at time of inspection Name of maintenance business: Smilies			
Sewage tank(s) leak below their designed operating depth?	☐ Yes* ☒ No	License number of maintenance business: 2428			
		Date of maintenance:	4/18/2021		
		☐ Existing tank integrity assessment (Attach)			
If yes, which sewage tank(s) leaks:		Date of maintenance (mm/dd/yyyy): (must be within	three years)		
Any "yes" answer above indicates the system is failing to protect groundwater.		(See form instructions to ensure assessment complies with Minn. R. 7082.0700 subp. 4 B (1))			
		☐ Tank is Noncompliant (pumping not necessary – explain below)			
		Other:			
Describe verification methods and results:					

roots are in tank, removed as much as possible.

3.	Other compliance conditions – Compliance component #3 of 5				
3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsecured? ☐ Yes* ☒ No ☐ Unknown					
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety? ☐ Yes* ☒ No ☐ *Yes to 3a or 3b - System is an imminent threat to public health and safety.				
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes* ☒ No			
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes* ☒ No			
	*Yes to 3c or 3d - System is failing to protect groundwater.				
	Describe verification methods and results:				
	pumped main tank and baffles are in place and roots in tank.				
	Attached supporting documentation: Not applicable				
1	Operating permit and nitrogen BMP* – Compliance component #4 or	f 5 ⊠ Not applicable			
		f "yes", A below is required			
	Is the system required to employ a Nitrogen BMP specified in the system design? Yes No I				
	BMP = Best Management Practice(s) specified in the system design	yes , b below is required			
	If the answer to both questions is "no", this section does not need to be completed	•			
	Compliance criteria:				
	a. Have the operating permit requirements been met? ☐ Yes ☐ No				
	b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No				
	Any "no" answer indicates noncompliance.				
	Describe verification methods and results:				
	Attached supporting documentation: Operating permit (Attach)				
	Attached supporting documentation. — Operating permit (Attach)				

https://www.pca.state.mn.us wq-wwists4-31b • 1/11/21

5. Soil separation – Compliance component #5 of 5

Date of installation 1/29/1976 (mm/dd/yyyy)	_		
Shoreland/Wellhead protection/Food beverage lodging?	☐ Yes ⊠ No	Attached supporting documentation: Soil observation logs completed for the	. , ,
Compliance criteria (select one): 5a. For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:	☐ Yes ⊠ No*	 ☐ Two previous verifications of required separation (Attach) ☐ Not applicable (No soil treatment area ☐ System will need to be above ground 	
Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.			
5b. Non-performance systems built April 1, 1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment: Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*	☐ Yes ☐ No*	Indicate depths or elevations A. Bottom of distribution media B. Periodically saturated soil/bedrock C. System separation D. Required compliance separation* *May be reduced up to 15 percent if allo Ordinance.	32" 12" 0" 24" wed by Local
5c. "Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules 7080. 2350 or 7080.2400 (Advanced Inspector License required) Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock. *Any "no" answer above indicates the			

Describe verification methods and results:

failing to protect groundwater.

Upgrade requirements: (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.