

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance: 5-27-16 Reason for Maintenance: Reg Main					
Property Address: 317 Hazel STW Property Owner's Name: Brian Boucher					
Municipality: 5/1/Water ZIP: 5508 Property Identification Number:					
Maintenance Permit No: W7049/62Z Maintainer Name and License No. Schiles 2428					
Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks l	NOT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ol> <li>Access used to remove septage:  Maintenance Hole Other (enter authorization code)</li> <li>Were all covers securely replaced? Yes No</li> <li>Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?</li> </ol>					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes 🖾 No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
er Til	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
Tank #1 gal Tank #2 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
	×				
	·				