## 1. Impact on public health - Compliance component #1 of 5 Compliance criteria: Attached supporting documentation: System discharges sewage to the ☐ Yes\* 🖾 No Other: ground surface ☐ Not applicable System discharges sewage to drain ☐ Yes\* 🛛 No tile or surface waters. System causes sewage backup into ☐ Yes\* 🖾 No dwelling or establishment. Any "yes" answer above indicates the system is an imminent threat to public health and safety. Describe verification methods and results: 2. Tank integrity – Compliance component #2 of 5 Compliance criteria: Attached supporting documentation: System consists of a seepage pit, ☐ Yes\* 🛛 No Pumped at time of inspection cesspool, drywell, leaching pit, or other pit? Name of maintenance business: ☐ Yes\* ☐ No Sewage tank(s) leak below their License number of maintenance business: designed operating depth? Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance 5/17/2021 (mm/dd/yyyy): If yes, which sewage tank(s) leaks: (must be within three years) Any "yes" answer above indicates the system (See form instructions to ensure assessment complies with Minn. R. 7082.0700 subp. 4 B (1)) is failing to protect groundwater. ☐ Tank is Noncompliant (pumping not necessary – explain below) Other: Describe verification methods and results: Tank pumped and verified by maintainer. Please see attached tank verification.