

OSTP Soil Observation Log

Project ID:

v 03.19.15



Client/ Address: 9767 Grey Cloud Island Drive South

Legal Description/ GPS:

2402722430004

Soil parent material(s): (Check all that apply)

- Outwash Lacustrine Loess Till Alluvium Bedrock Organic Matter

Landscape Position: (check one)

- Summit Shoulder Back/Side Slope Foot Slope Toe Slope Slope shape

Vegetation

Lawn

Soil survey map units

Slope%

6.0

Elevation:

Weather Conditions/Time of Day:

Warm 8:00 am

Date

05/24/21

Observation #/Location:

See map

Observation Type:

Auger

Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Structure		
							Shape	Grade	Consistence
0-20"	Loamy Sand	<35%	7.5YR 3/3				Blocky	Weak	Loose
20-40"	Sandy Loam	<35%	7.5YR 4/4				Blocky	Weak	Loose
40-60"	Loamy Sand	<35%	7.5YR 4/4				Blocky	Weak	Loose
Comments									

I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.

Shelley Schlomka

41367

5/24/2021

(Designer/Inspector)

(Signature)

(License #)

(Date)