## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintenar	nce 10-19-15 Reason fo	or Maintenance:	outire		
Property Address:	810 Oakgreen	Ave N Property	Owner's Name: $\mathcal{D}\mathcal{C}_{\mathcal{A}}$	nise Kubaa	ke.
Municipality:	tillwester	State 120 Zip Code _	GEO Coo	de/Property I.D. #:	
- What wa	s done to the system?	Tank Measu	rements (must be com	pleted if tanks NOT pumpe	:d)
Tank(s) Pumpe	ed .	Liquid Level of Tank	in. Sludge Le	<sub>evel</sub> in. Scum Level	in.
<ul> <li>☐ Sludge and scum measured.</li> <li>Do tanks need to be pumped?</li> <li>☐ Yes</li> <li>☐ No (If no provide measurements)</li> </ul>					<del></del>
		Total (Sludge + Scum	) / Liquid Leve	≘l = % Sludge & Scu ——	ım
1. Access used to	remove septage: Mainten	ance Hole Other (Go	to #3 below)	* Tank must be pumped if is greater than 25%.	this value
2. If maintenance	hole was used, were all covers	securely replaced? Y	es 🔲 No <b>please expl</b> o		
Explanation:		•			
	es to allow a Subsurface Sewa and sign the following state		SSTS) to be pumped ti	nrough the maintenance ho	le, have
I,	(ov	vner's name), refuse to all	ow the removal of solid	ls and liquids through the ma	intenance
hole. I understa	and that removal of solids and	liquids through other acc	ess points is not consid	ered maintenance.	
4. Is the tank design	gned as a leaky tank? example:	seepage pit, cesspool, dryv	vell, leaching pit		
Tank#1 📘 Ye	s No Verificatio Method	Used:			
Tank#2 Tank#2	s No Verificatio Method	Used:			
	nce of tank leakage from a se			ow the operating depth or e	evidence of
damaged, crac	ked, or structurally unsound  Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No	Yes No	Yes No	
	Septic/Holding Tank #2	Yes No	Yes No	Yes No	
	Pretreatment Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	Yes No	T Yes No	
6. How many gal	lons of septage were remove	ed?			
Tank #1 /50	V Tank #2 1000	Pretreatment Tanl	· Ρι	ump Tank	
7. Other informa	tion: List any troubleshootin	ng, minor repairs conduc	ted, tank safety conc	erns, or other concerns.	
	I hereby certify as a State of M and made the observations, o	r directly supervised othe	rs in the performance o	of this job.	
Maintainer's Na	ame: PINKY'S SEWER SERVICE	Maintainer'	s Address: P.O. Box 354	Afton, MN 55001	
Maintainer's Li	cense #: 1673 Mainta	iner's Phone #; 651-439-	4847		
Maintainer's Si	gnature All		Date: <b>/ 0</b> ·	-19-15	