## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintena	ince 10-8-15 Reason 1	for Maintenance: XCU	tiru		
Property Address	= 730 Norch P	<del></del> -	Owner's Name: <u>((</u> )	- 1 (0 1)	<u> </u>
Municipality:	Shilmerto	State MU Zip Code S	55682 GEO Cod	e/Property I.D. #:	
What w	as done to the system?	Tank Measure	ements (must be com	pleted if tanks NOT pumped	)
Do tanks nee	ted cum measured. d to be pumped? No ( <i>if no provide measu</i> remen	Liquid Level of Tank Total (Sludge + Scum)	in. Sludge Le	= % Sludge & Scum	
1. Access used to	remove septage: Mainte	nance Hole 🔲 Other (Go t	ø #3 below)	<ul> <li>Tank must be pumped if the is greater than 25%.</li> </ul>	nis value
2. If maintenance	hole was used, were all cover	s securely replaced?	s 🔲 No <b>please expl</b> a	<del>-</del>	
Explanation:					
3. If owner refus	es to allow a Subsurface Sew e and sign the following stat		STS) to be pumped th	rough the maintenance hole	, have
ι,	<del></del>			s and liquids through the main	itenance
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.					
4. Is the tank desi	igned as a Je <del>a</del> ky tank? <i>example</i>	e: seepage pit, cesspool, drywe	ell, leaching pit		
Tank#1 🔲 Ye	es No Verificatio Method	d Used:		·	<u>.                                     </u>
Tank#2 🎵 Ye	es No Verificatio Method	d Used:			
	nce of tank leakage from a s cked, or structurally unsoun			ow the operating depth or ev	idence of
dumagea, cra	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No	Yes No	☐ Yes ☐ No	
	Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	Yes No	
	Pretreatment Tank	Yes No	☐ Yes ☐ No	Yes No	
	Pump Tank	Yes No	Yes No	Yes No	
6. How many ga	llons of septage were remov	ved?			
Tank#1 1500 Tank#2		Pretreatment Tank Pum		mp Tank	
7. Other inform	ation: List any troubleshooti	ing, minor repairs conduct	ed, tank safety conce	erns, or other concerns.	
8. Certification:	I hereby certify as a State of I and made the observations,	or directly supervised other	s in the performance o	f this job.	
Maintainer's N	lame: PINKY'S SEWER SERVICE	E Maintainer's	Address: P.O. Box 354	Afton, MN 55001	
Maintainer's L	icense #: 1673 Maint	ainer's Phone #: 651-439-4	847		
Maintainer's S	ignature / ///	Marie	Date: )	0-8-15	