

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety					
prior to performing maintenance	y to constitute a v	alid maintenance p	ermit. This permit	must be completed	
<u>prior</u> to performing maintenance activi	ities and remain o	n-site for the dura	tion of the maintena	nce activity.	
Date of Maintenance: 4-21-21 Reason	n for Maintenance:	Kautru	L		
Property Address: 1760 53rd S	it w	Property Owner's N	lame: Themes	Stefens	
Municipality: CULL FIMO ZIP: 556	Property Ide	entification Number			
Maintenance Permit No: <u>V35%5 L22218</u>	Maintainer Name		•		
	Maritainer Name a	nd License No. Pink	y's Environmental Se	wer Service/ L1673	
Maintenance Performed	Tank Mea	surement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped		Tank — in			
☐ Sludge and scum measured	Sludge Level in		Scum Level in Tank	in	
Do tanks need to be pumped?		Sludge + Scum			
\square Yes \square No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to remove septage: Maintena	ince Hole Other (omton outland it			
 Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structur 	otic, holding, pretr ally unsound main	reatment or pump tenance hole cove	tank below the oper rs? Yes No	ating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No				
		Yes No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ No		
Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☐ No☐ Yes ☐ No☐				
		☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No		
Pretreatment Tank Pump Tank 4. How many gallons of septage were removed?	☐ Yes ☐ No ☐ Yes ☐ No ?	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		
Pretreatment Tank Pump Tank 4. How many gallons of septage were removed: Tank #1 / SDD gal Tank #2	☐ Yes ☐ No ☐ Yes ☐ No ? gal Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tankga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal	
Pretreatment Tank Pump Tank 4. How many gallons of septage were removed: Tank #1 1500 gal Tank #2 5. Other information: List any troubleshooting,	Yes No Yes No Yes No gal Pretreatment minor repairs con	Yes No Yes No Yes No tank ga	Yes No Yes No Yes No Pump Tank Yes on other	concerns	
Pretreatment Tank Pump Tank 4. How many gallons of septage were removed: Tank #1 1500 gal Tank #2 5. Other information: List any troubleshooting, Manhole in flour garles, cann	Yes No Yes No Yes No gal Pretreatment minor repairs con	Yes No Yes No Yes No tank ga	Yes No Yes No Yes No Yes No Pump Tank y concerns, or other	concerns.	
Pretreatment Tank Pump Tank 4. How many gallons of septage were removed: Tank #1 1500 gal Tank #2 5. Other information: List any troubleshooting, Manhole in flour garles, cann	Yes No Yes No Yes No gal Pretreatment minor repairs con	Yes No Yes No Yes No tank ga	Yes No Yes No Yes No Yes No Pump Tank y concerns, or other	concerns.	
Pretreatment Tank Pump Tank 4. How many gallons of septage were removed: Tank #1 / SOO gal Tank #2 5. Other information: List any troubleshooting,	Yes No Yes No Yes No gal Pretreatment minor repairs con	Yes No Yes No Yes No tank ga	Yes No Yes No Yes No Yes No Pump Tank y concerns, or other	concerns.	

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673