

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

## Subsurface Sewage Treatment System Maintenance Permit

This section must be				,	Tarree Terrific	
This section must be com	pleted in its entirety	to constitute a v	alid maintenance p	permit. This permit	must be complete	
	maintenance activit	ies and remain o	n-site for the dura	tion of the maintena	ince activity.	
Date of Maintenance: 4-	Reason	for Maintenance:	Reutine			
Property Address: 8131	75° St.	MC	Property Owner's I	Name: PUTICK	Farrell	
Municipality: Stillug	ter zip: 550	82 Property Ide	entification Number			
Maintenance Permit No:	78/422473	Animtois su No				
Maintenance Permit No:		Maintainer Name a	nd License No. Pini	ky's Environmental Se	ewer Service/ L167	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank — in				
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater				
					ii 25% or greater	
1. Access used to remove s			enter authorization c	ode)		
<ol><li>Were all covers securely</li></ol>						
3. Is there evidence of tan	k leakage from a sep	tic, holding, preti	eatment or pump	tank below the oper	rating depth or	
evidence of damaged,	cracked, or structura	ally unsound main	tenance hole cove	ers? 🗌 Yes 🖳 No	acing depth of	
	Tank	Leaking Out	Leaking In	Cover Damage		
Septio	c/Holding Tank #1	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
Septio	c/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretre	eatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump	Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
. How many gallons of sep	tage were removed?					
Tank #1 gal	Tank #2	gal Pretreatment	tank ga	al Pump Tank	an.l	
. Other information: List a	ny troubleshooting	minor repairs cor	ducted tank safe	transprank	gat	
System too or	le for manhal	e con				
	, , , , , , , , , , , , , , , , , , , ,					
Location of sentage dispos	al ed Devil					
. Location of septage dispos	sal: 37. Faul					
	Pinky's	Environmental Se	wer Service Inc.			
		PO Box 35	4			

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001 P: 651-439-4847 License Number: L1673