## Impact on public health – Compliance component #1 of 5 Compliance criteria: Attached supporting documentation: ☐ Yes\* 🖾 No System discharges sewage to the Other: ground surface ☐ Not applicable ☐ Yes\* ☒ No System discharges sewage to drain tile or surface waters. System causes sewage backup into ☐ Yes\* 🖾 No dwelling or establishment. Any "yes" answer above indicates the system is an imminent threat to public health and safety. Describe verification methods and results: 2. Tank integrity – Compliance component #2 of 5 Compliance criteria: Attached supporting documentation: System consists of a seepage pit, ☐ Yes\* 🛛 No Pumped at time of inspection cesspool, drywell, leaching pit, or other pit? Name of maintenance business: Meyers ☐ Yes\* 🛛 No Sewage tank(s) leak below their License number of maintenance business: designed operating depth? Date of maintenance: 6/8/2021 ☐ Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years) If yes, which sewage tank(s) leaks: (See form instructions to ensure assessment complies with Any "yes" answer above indicates the system Minn. R. 7082.0700 subp. 4 B (1)) is failing to protect groundwater. ☐ Tank is Noncompliant (pumping not necessary – explain below) Other: Describe verification methods and results: