Parcel number:	, w	_ System status: Compliant No	oncompliant	
		(as determined by this form)		197
	and the second second		•	
Tank Integrity and Safety Co	mpliance		2	
Compliance Issue #2 of 4	, , , , , , , , , , , , , , , , , , ,	Routine Pumpir		
Date of observation: 5/28/202	The state of the s	HOIL	'9	
This form expires on (three years):	5/27	7/2024		
Compliance questions/criteria: (Requ	Verification Method**: (Optiona	1)		
(Check the appropriate box)		(Check the appropriate box)		6
Does the system consist of a seepage pit*, cesspool, drywell, or leaching pit?	Yes X No	Probed tank bottom		
Do any sewage tank(s) leak below their	Yes No	Observed low liquid level		
designed operating depth?		☐ Examined construction record		
If yes, identify which sewage tank leaks.	Examined empty (pumped) to			
Any "yes" answer indicates that the system	☐ Probed outside tank for *black ☐ Pressure/vacuum check	K SOII		
ground water.				
* Seepage pits meeting 7080.2550 may be compliant if allowed				
in ordinance by local permitting authority.		** No standard protocol exists. This lis	et ie not avhaueti	ive in
		sequential order, nor does it indicate	te which combina	
		are necessary to make this determi	nation.	
Safety Check				_
Are any maintenance hole covers damaged, cracked, or appeared to be structurally unsound?				No No
Were all maintenance hole covers replaced in a secured manner (e.g., all screws replaced)?				□ No*
Was secondary access restraint present (safety pan, second cover, or safety netting) – highly recommended.				No No
4. Was any other safety/health issue present?			☐ Yes*	X No
*System is an imminent threat to public health and safety.				
"System is an imminent threat to pu	buc neaun and salety.			
Certification		*		
This form is to be completed and attached t	to the Summary Form of the	e Minnesota Pollution Control Agency's	(MPCA) Comp	liance
Inspection Form for Existing Subsurface completed by an inspector, maintainer, or s	Sewage Treatment System	ems. Observations, interpretations, and	conclusions mu	ust be
15 days.	ervice provider. Completed	Tom must be submitted to the local dis	t or government	r Astralia
Property owner name(s):	Nathan John	ison		
Property address:	80 Quality Ave N L	akeland MN	-	
Property owner's address (if different):				
	ington			
3	N .		The same of the sa	
1-hereby certify that I personally made the o correct.	uservauons, interpretations	s, ана сонстияють героняа от this form	anu ulat mey a	16
Name Larry Schlomk	(ai	Certification number:	253	ŝ
Business license name and number:	Schlomka Serv			or
Name of local unit of government:				
Signature: 7-1/5di-L Date:				