3. Other compliance conditions – Compliance component #3 of 5		
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsecured? ☐ Yes* ☐ No ☐ Unknown	
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safet *Yes to 3a or 3b - System is an imminent threat to public health and safety.	y? ☐ Yes* ☒ No ☐ Unknown
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes* ☒ No
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes* ⊠ No
	*Yes to 3c or 3d - System is failing to protect groundwater.	
	Describe verification methods and results:	
	2001.B0 Vollingation incursors and recursor.	
	Attached supporting documentation: Not applicable	
4.	Operating permit and nitrogen BMP* – Compliance component #4 o	f 5 Not applicable
	Is the system operated under an Operating Permit? ☐ Yes ☐ No	f "yes", A below is required
	Is the system required to employ a Nitrogen BMP specified in the system design? Yes No	f "yes", B below is required
	BMP = Best Management Practice(s) specified in the system design	
	If the answer to both questions is "no", this section does not need to be completed	i.
	Compliance criteria:	
	a. Have the operating permit requirements been met? ☐ Yes ☐ No	
	b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No	
	Any "no" answer indicates noncompliance.	
	Describe verification methods and results:	
	Attached supporting documentation: ☐ Operating permit (Attach) ☐	
	Attached supporting documentation: Operating permit (Attach)	

https://www.pca.state.mn.us wq-wwists4-31b • 1/11/21