1. Impact on public health - Compliance component #1 of 5 Compliance criteria: Attached supporting documentation: System discharges sewage to the ☐ Yes* ⊠ No ☐ Other: ground surface ☐ Not applicable System discharges sewage to drain ☐ Yes* ☑ No tile or surface waters. System causes sewage backup into ☐ Yes* ☒ No dwelling or establishment. Any "yes" answer above indicates the system is an imminent threat to public health and safety. Describe verification methods and results: 2. Tank integrity – Compliance component #2 of 5 Compliance criteria: Attached supporting documentation: System consists of a seepage pit, ☐ Yes* ☐ No ☐ Pumped at time of inspection cesspool, drywell, leaching pit, or other pit? Name of maintenance business: Sewage tank(s) leak below their ☐ Yes* 🛛 No License number of maintenance business: designed operating depth? Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance 5/28/2021 (mm/dd/yyyy): If yes, which sewage tank(s) leaks: (must be within three years) Any "yes" answer above indicates the system (See form instructions to ensure assessment complies with Minn. R. 7082.0700 subp. 4 B (1)) is failing to protect groundwater. ☐ Tank is Noncompliant (pumping not necessary – explain below) Other: Describe verification methods and results: