Parcel number:	System status: Compliant No	ncompliant		
		(as determined by this form)		¥
Taula lada suide and Cafada Ca			•	
Tank Integrity and Safety Compliance				
Compliance Issue #2 of 4 Second for absorption: Routine Pumping				
Date of observation: SIZOIZOZI Reason for observation.				
This form expires on (three years): 5/27/2024				
Compliance questions/criteria: (Requ	Verification Method**: (Optional))		
(Check the appropriate box)		(Check the appropriate box)		
Does the system consist of a seepage pit*, cesspool, drywell, or leaching pit?	☐ Yes 🛣 No	Probed tank bottom		
Do any sewage tank(s) leak below their	Yes No	Observed low liquid level		
designed operating depth?		Examined construction records		
If yes, identify which sewage tank leaks.	Examined empty (pumped) tank			
Any "yes" answer indicates that the system	Probed outside tank for "black soil"			
ground water.		☐ Pressure/vacuum check		
* Seepage pits meeting 7080.2550 may be	Other:			
in ordinance by local permitting authority.		** No standard protocol eviets. This lis	t is not exhau	retive in
** No standard protocol exists. This list is not exhaustive, in sequential order, nor does it indicate which combinations				
	<u> j</u>	are necessary to make this determin	iation.	
Safety Check			<u> </u>	
Are any maintenance hole covers damaged, cracked, or appeared to be structurally unsound?			∐ Yes*	No No
2. Were all maintenance hole covers replaced in a secured manner (e.g., all screws replaced)?			Yes	□ No*
3. Was secondary access restraint present (safety pan, second cover, or safety netting) – highly recommended.			∐ Yes	No No
4. Was any other safety/health issue present?			☐ Yes*	X No
Explain:				
*System is an imminent threat to public health and safety.				
Certification				
This form is to be completed and attached to the Summary Form of the Minnesota Pollution Control Agency's (MPCA) Compliance				
Inspection Form for Existing Subsurface completed by an inspector, maintainer, or s	Sewage Treatment Syster	ns. Observations, interpretations, and	conclusions i	must be
15 days.	ervice provider. Completed i	offi must be submitted to the local drift	or governme	STE AMELIE
Property owner name(s):	Aggregate Indus	stries		
	rey Cloud Island Dr.	Cottage Grove MN		
Property owner's address (if different):				
County: Washington Phone:				
I-hereby certify that I personally made the o	bservations, interpretations,	and conclusions reported on this form	and that they	y are
Name. Larry Schlomk	ra.	Certification number: C42	253	
Business license name and number:	Schlomka Servi	Octobodi Hambor.		or
Comment				
Name of local unit of government: Signature: Date: 6/4/2021				
Signature: /-//>	1		- 14 Feb. 11	