

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	maintenance activitie			A STATE OF THE PARTY OF THE PAR	HARLIE TERRETOR EZ. (ERZASTELLATA BARTANOS CHIPA
Date of Maintenance: 6 2					io decivity.
Property Address: 11222				e: Richarda Ja	net Jacka
Municipality: Stillustor	ZIP: 5508	Property Identif	fication Number:		
Maintenance Permit No: M				Sower Service / L	
Table 1 chime	Mai	ntamer Name and E	icense No. <u>Simile s</u>	s sewer service / L z	.420
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
→ Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank ——— in Scum Level in Tank——— in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
Yes No (if no provide measurements)					
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
2. Were all covers securely	replaced? ✓ Yes	No			
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or					
evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes \times No					
	Tank	Leaking Out	Leaking In	Cover Damage	
Septio	/Holding Tank #1	Yes No	Yes No	Yes No	
Septio	/Holding Tank #2	Yes No	_ Yes No	Yes No	
Pretre	eatment Tank	Yes No	_ Yes No	Yes No	
Pump	Tank	Yes No	_ Yes No	Yes No	
4. How many gallons of sep					
Tank #1gal	gal Pretreatment ta	nkgal	Pump Tank	gal	
5. Other information: List a					
				,	
6. Location of septage dispos	sal: Land	Applied			
		Smilie's Sewer Ser	vice		
P.O. Box 100					
*		Scandia, MN 550			
	P: 651-4	33-3934 License N	lumber: L2428		
Maintenance activities must be reported to the Department within 90 days.					

White Copy-Maintainer submits to Washington County / Yellow Copy-Property Owner Record