## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

Date of Maintenance (1)   Reason	n for Maintenance:	3632, 32,	393	
Property Address: 15729	AV.N. Prope	erty Owner's Name:	Pob Ellman	
Municipality:	State Zip Code		ode/Property I.D. #:	
What was done to the system?	Tank Mea	surements (must be co	impleted if tanks NOT pump	ēd)
Tank(s) Pumped	Liquid Level of Tar	ık in. Sludge	Level in. Scum Level	in.
Sludge and scum measured.	Liquid Level of Tar			
Do tanks need to be pumped?	Total (Sludge + Sci	um) / Liquid Le	vel = % Sludge & Sc	um *
Yes No (If no provide measureme			* Tank must be pumped i	f this value
1. Access used to remove septage: Maint	a la		is greater than 25%.	
2. If maintenance hole was used, were all covered to the maintenance hole was used, were all covered to the maintenance hole was used, were all covered to the maintenance hole was used, were all covered to the maintenance hole was used, were all covered to the maintenance hole was used.	ers securely replaced?	Yes No please exp	plain	
Explanation:				((
3. If owner refuses to allow a Subsurface Se them complete and sign the following sta		n (SSTS) to be pumped	through the maintenance ho	ole, have
I, (	owner's name), refuse to	allow the removal of sol	ids and liquids through the ma	intenance
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.				
4. Is the tank designed as a leaky tank? example	le: seepage pit, cesspool, d	rywell, leaching pit		
Tank#1 Yes No Verificatio Metho	od Used: Pump	ed Tank		
Tank#2 Yes No Verificatio Metho	od Used:			
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?				
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	Yes No	Yes No	
Septic/Holding Tank #2	☐ Yes ☐ No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	☐ Yes ☐ No	
Pump Tank	Yes No	☐ Yes ☐ No	Yes No	
6. How many gallons of septage were remo	ved?			
Tank #1 1200 Tank #2 Pretreatment Tank Pump Tank				
7. Other information: List any troubleshoot	ing, minor repairs cond	ucted, tank safety cond	erns, or other concerns.	
8. Certification: I hereby certify as a State of and made the observations,  Maintainer's Name: Olson's Sewer Service,	or directly supervised ot	ners in the performance	ally conducted the work of this job.  as Street NE, Forest Lake, MN	
-		-		
Maintainer's License #: 216 Maint	tainer's Phone #: 651-46	4-2082		
Maintainer's Signature		Date:	(20210113	