## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintena	ince 11-18-15 Reason for	Maintenance: 20	Aine		
Property Address	7481 Branada Ba	7 S. Property	Owner's Name: <u>Bill</u>	Baker	
Municipality:	offage Grove	itate $\mu\nu$ Zip Code	55016_ GEO Cod	e/Property I.D. #:	
What w	as done to the system?	Tank Measu	rements (must be com	pleted if tanks NOT pumped)	
☐ Tank(s) Pumped ☐ Sludge and scum measured. ☐ Do tanks need to be pumped? ☐ Yes ☐ No (If no provide measurements)		Liquid Level of Tank Total (Sludge + Scum	in. Sludge Le		in. — *
1. Access used to	remove septage: Maintena	nce Hole Other (Go	to #3 below)	* Tank must be pumped if the is greater than 25%.	is value
	e hole was used, were all covers s			_	
		,			
Explanation: _	ses to allow a Subsurface Sewa	- Treatment System (	SSTS) to be numbed th	rough the maintenance hole	
	es to allow a Subsurface Sewa e and sign the following state:		3313) to be painted a	lough the mantenance note	,
l,	(ow	ner's name), refuse to al	low the removal of solid	s and liquids through the main	tenance
hole. I underst	tand that removal of solids and li				
	igned as a leaky tank? example: s				
Tank#1 🗀 Y	es No Verificatio Method L	Jsed:			
***************************************					
***************************************	es Mo Verificatio Method (		<u> </u>		
5. Is there evide	ence of tank leakage from a sep ocked, or structurally unsound	itic, holding, pretreatn maintenance hole cove	nent or pump tank beld ers?	ow the operating depth or ev	idence of
damaged, cra	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	T Yes TNo	☐ Yes ☐ No	Yes No	
	Septic/Holding Tank #2	Yes Wo	Yes LAO	Yes Z-No	
	Pretreatment Tank	Yes No	☐ Yes ☐ No	Yes No	
	Pump Tank	Yes No	☐ Yes ☐ No	Yes No	
6. How many ga	allons of septage were remove	d?			
Tank #1 /28	7 Tank #2 /250	Pretreatment Tar	ık Pı	ımp Tank	
7. Other inform	ation: List any troubleshooting	g, minor repairs condu	cted, tank safety conce	erns, or other concerns.	
	•				
8. Certification	: I hereby certify as a State of Mi and made the observations, or	directly supervised oth	ers in the performance o	f this job.	
Maintainer's I	Name: PINKY'S SEWER SERVICE	Maintaine	r's Address: P.O. Box 354	Afton, MN 55001	
		ner's Phone #: 651-439	-4847		
Maintainer's	Signature The Of	plo .	Date: //	-18-6	