



Client/ Address: Kristi Rose 7793 132nd Street N Hugo		Legal Description/ GPS: 2703121430006	
Soil parent material(s): (Check all that apply)			
<input type="checkbox"/> Summit <input checked="" type="checkbox"/> Shoulder <input type="checkbox"/> Back/Side Slope <input type="checkbox"/> Foot Slope <input type="checkbox"/> Toe Slope <input type="checkbox"/> Alluvium <input type="checkbox"/> Bedrock <input type="checkbox"/> Organic Matter <input type="checkbox"/> Outwash <input type="checkbox"/> Lacustrine <input type="checkbox"/> Loess <input checked="" type="checkbox"/> Till			
Landscape Position: (check one)		Slope shape	
<input type="checkbox"/> Summit <input checked="" type="checkbox"/> Shoulder <input type="checkbox"/> Back/Side Slope <input type="checkbox"/> Foot Slope <input type="checkbox"/> Toe Slope		Convex - Convex	
Vegetation	Lawn	Soil survey map units 504D	Elevation:
Weather Conditions/Time of Day: Very hot - sunny 4:00 pm		Slope%	Date 06/11/21
Observation #/Location: See map		Observation Type: Auger	
Depth (in)	Texture	Rock Frag. %	Indicator(s)
0-4"	Loam	<35%	10YR 3/3
4-32"	Loamy Sand	<35%	10YR 4/3
32-60"	Silt Loam	<35%	10YR 3/4
Comments Obstruction at 60" 1 - 3" rock in yard.			
I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.			
Shelley Schiomka		4137	6/11/2021
(Designer/Inspector)		(License #)	(Date)