DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance (1)5 Z1 Reason	on for Maintenance:	1902 + 22	599	
Property Address: 6377 - 18475	it.N. Pro	perty Owner's Name:	1 & Debra Kozak	
Municipality: Trust date	State Zip Co	de <u>5500</u> GEO (Code/Property I.D. #:	
What was done to the system?	A Francisco	aylıkembilga (bineypa)	ompleted (frank NOT pumped).	
Tank(s) Pumped	Liquid Level of Ta	ank in. Sludge	Level in Scum Level	in.
Sludge and scum measured. Do tanks need to be pumped?	1			
Yes No (If no provide measureme	Potal (Sludge + S	cum) / Liquid Le	evel = % Sludge & Scum	
1. Access used to remove septage: Maint		(Go to #3 below)	* Tank must be pumped if this valis greater than 25%.	ue
2. If maintenance hole was used, were all covered to the covered t	ers securely replaced?	Yes No please exp	lain	
Explanation:			,	
3. If owner refuses to allow a Subsurface Se them complete and sign the following sta	wage Treatment Syste	m (SSTS) to be pumped	through the maintenance hole, have	<u>-</u>
l, (Owner's name) refuse to	allow the removal of soli	ds and liquids through the maintenan	
hole. I understand that removal of solids an				ce
4. Is the tank designed as a leaky tank? example				
Tank#1 Yes No Verificatio Metho	od Used:			
Tank#2 Yes No Verificatio Metho	d Used:			_
5. Is there evidence of tank leakage from a s	eptic, holding, pretrea	tment or pump tank be	ow the operating depth or evidence	
damaged, cracked, or structurally unsoun	d maintenance hole co	overs?		. ••
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	Yes No	Yes No	
Septic/Holding Tank #2	☐ Yes ☑ No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes No	Yes No	Yes No	
6. How many gallons of septage were remov	red?			
Tank #1	Pretreatment Ta	ınk Pı	ımp Tank	
				
7. Other information: List any troubleshooti	ng, minor repairs cond	ucted, tank safety conce	erns, or other concerns.	
D Contifications house, with a Contification	A:			_
B. Certification: I hereby certify as a State of M and made the observations, or	nnesota certified 5515 or directly supervised ot	Maintainer that I persona ners in the performance o	lly conducted the work f this iob.	
Maintainer's Name: Olson's Sewer Service, I			Street NE, Forest Lake, MN	
Maintainer's License #: 216 Mainta	niner's Phone #: 651-46	4-2082		_
770)	mier 3 i none w. 031-40	- 2002	4	
Maintainer's Signature	Mey	Date:	2 (5.21	