DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

| Date of Maintena | nce 10-26-1 Beason for | Maintenance: | withe | | |
|--|---|---|------------------------|--|---------------|
| Property Address: | 7479 PINEHUNG | Troperty (| Owner's Name: Cip | dy Rondea | Ц |
| Municipality: | iaptomodis | tate $ u$ Zip Code $_$ | GEO Code | e/Property I.D. #: | |
| What wa | as done to the system? | Tank Measur | ements (must be com | pleted if tanks NOT pumped) | |
| Do tanks need | ed rum measured. d to be pumped? No (If no provide measurements) | Liquid Level of Tank Total (Sludge + Scum) | in. Sludge Le | = % Sludge & Scum | in. — * |
| 1. Access used to | remove septage: Maintenar | nce Hole Dother (Go | #3 below) | * Tank must be pumped if th is greater than 25%. | is value |
| 2. If maintenance | hole was used, were all covers se | ecurely replaced? | s 🦲 No please expla | _ | |
| Explanation: | | | | | |
| 3. If owner refuse them complete | es to allow a Subsurface Sewag e and sign the following staten | je Treatment System (S nent: | STS) to be pumped th | rough the maintenance hole, | have |
| I, (owner's name), refuse to allow the removal of solids and liquids through the maintenance | | | | | |
| hole. I understand that removal of solids and liquids through other access points is not considered maintenance. | | | | | |
| 4. Is the tank desi | gned as a Jeaky tank? example: se | epage pit, cesspool, dryw | ell, leaching pit | | |
| Tank#1 📘 Ye | es No Verificatio Method U | sed: | | | |
| Tank#2 ☐ Ye | es No Verificatio Method U | sed: | | | |
| 5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? | | | | | |
| | Tank | Leaking Out | Leaking In | Cover Damage | |
| | Septic/Holding Tank #1 | Yes No | TYes JNO | Yes Alo | |
| | Septic/Holding Tank #2 | ☐ Yes ☐ No | Yes No | Yes No | |
| | Pretreatment Tank | Yes No | Yes No | Yes No | |
| | Pump Tank | Yes No | Yes No | ☐ Yes ☐ No | |
| 6. How many ga | llons of septage were removed | 1? | | | |
| Tank #1 1 3 Tank #2 Pretreatment Tank Pump Tank | | | | | |
| 7. Other informa | ation: List any troubleshooting | , minor repairs conduc | ted, tank safety conce | rns, or other concerns. | |
| 8. Certification: | I hereby certify as a State of Mir and made the observations, or | directly supervised other | s in the performance o | f this job. | |
| Maintainer's N | lame: PINKY'S SEWER SERVICE | Maintainer's | Address: P.O. Box 354 | Afton, MN 55001 | |
| Maintainer's L | icense #: 1673 Maintain | er's Phone #: 651-439-4 | | , | |
| Maintainer's S | ignature / | //wan | Date: | D-76×15 | |