DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance Reason	on for Maintenance:	molience	*M281P 135 d.	10
Property Address: 14900 . 223	St. Prope	rty Owner's Name	about Kemmis	
Municipality:	State Zip Code	GEO	Code/Property I.D. #:	
What was done to the system?	子 字等:Tank Mea	urements (mustiber	ompleted if tanks NOT pumpe	d) -
Tank(s) Pumped	Liquid Level of Tan	in Chale	e Level in. Scum Level	in.
Sludge and scum measured.	Elquid Level OF Fami	in. Sludg	e revel 2cam revel	
Do tanks need to be pumped? Yes No (If no provide measurem	ents) Total (Sludge + Scu	m) / Liquid L	evel = % Sludge & Scu	m
1. Access used to remove septage: Main	tenance Hole Other (G	io to #3 below)	 * Tank must be pumped if is greater than 25%. 	this value
2. If maintenance hole was used, were all cov	ers securely replaced?	Yes No please ex	_	
Explanation:				3.
3. If owner refuses to allow a Subsurface So them complete and sign the following st	ewage Treatment System atement:	(SSTS) to be pumped	through the maintenance ho	e, have
l,	(owner's name), refuse to a	llow the removal of so	lids and liquids through the mai	ntenance
hole. I understand that removal of solids ar			,	
4. Is the tank designed as a leaky tank? examp	le: seepage pit, cesspool, dry	well, leaching pit		
Tank#1 Yes No Verificatio Metho	od Used: Pumper	1 Tunk		
Tank#2 Yes No Verificatio Metho	od Used:			
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsou			elow the operating depth or ex	idence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	Yes No	Yes No	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes No	Yes ANO	Yes No	
6. How many gallons of septage were remo	ved?			
Tank #1 1500 Tank #2	Pretreatment Tan	k F	Pump Tank 400	
7. Other information: List any troubleshoot	ing, minor repairs condu	cted, tank safety cond	erns, or other concerns.	
8. Certification: I hereby certify as a State of	Minnocota cortified SSTS M	aintainer that I nercen	ally conducted the work	
and made the observations,				
Maintainer's Name: Olson's Sewer Service,	Inc. Maintainer	s Address: 17638 Lyor	s Street NE, Forest Lake, MN	
Maintainer's License #: 216 Maint	ainer's Phone #: 651-464-	2082		
Maintainer's Signature		Date:	7/21/21	
			N. N.	