

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be con	npleted in its entirety	to constitute a va	lid maintenance p	ermit. This permit n	nust be complete
prior to performin	ng maintenance activiti	es and remain or	-site for the durat	ion of the maintenar	nce activity.
Date of Maintenance: 5					
Property Address: 201	5 ochkyrcen	Are No	Property Owner's N	ame: Saran	Vernberg
Municipality: Sthu	Uter ZIP: 500	Property Ide	ntification Number:		
Maintenance Permit No	6072; 22714 M	aintainer Name a	nd License No. Pink	e's Environmental Car	
		The traine at	id License No. Filik	y's Environmental Sev	ver Service/ L167
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove					
 Were all covers secure Is there evidence of ta evidence of damaged, 	nk leakage from a sept	ic, holding, pretr	eatment or pump t	ank below the opera	iting depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
Sep	tic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☑ No	
Sep	tic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pret	reatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pum	p Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1 25 gal	ptage were removed? Tank #2	al Pretreatment	tank		
. Other information: List	any troubleshooting, n	ninor repairs con	ducted tank safety	rump Tank	gal
			adeted, tallk salety	concerns, or other	concerns.
. Location of septage dispo	osal: St faul				
	Pinky's E	invironmental Sev			
		PO Box 354			

Afton MN 55001 P: 651-439-4847 License Number: L1673