DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance (Rea	son for Maintenance:	A W09394	22912	
Property Address: Ann - 204th	St.NI. P	operty Owner's Name:	Corge & Marilyn	matt
Municipality: Just Jak	State NV Zip C	ode 55 025 GEO	Code/Property I.D. #:	116114
What was done to the system?	The state of the state of	ព្រះអាចការ៉ាអ្នកព្រំកេសវិវិទ	សមាន ដែញស្រែក្រុស្តា	(d)
Tank(s) Pumped	Liquid Level of	Tank in Sluda		
Sludge and scum measured. Do tanks need to be pumped?	J. Salara Science	11. Sludg	e Level in. Scum Level	in.
Yes No (If no provide measuren	Total (Sludge +	Scum) / Liquid L	evel = % Sludge & Sc	um
1. Access used to remove septage:		er (Go to #3 below)	* Tank must be pumped i	f this value
2. If maintenance hole was used, were all cov			is greater than 25%.	· ····································
Explanation:	(The please ex	piain	,
3. If owner refuses to allow a Subsurface So them complete and sign the following st	ewage Treatment Syst	em (SSTS) to be pumped	through the maintenance ho	le, have
hole. I understand that removal of solids as	(Owner's name), refuse to	o allow the removal of sol	ids and liquids through the mai	ntenance
4. Is the tank designed as a leaky tank? examp	le: seepaae nit. cessnool	drivell leaching nit	dered maintenance.	
Tank#1 Yes No Verificatio Metho		ary wen, reaching pit		
Tank#2 Yes Pro Verificatio Metho				
5. is there evidence of tank leakage from a damaged, cracked, or structurally unsour	septic, holding, pretre	atment or pump tank be	low the operating depth or ev	idence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	Yes TONO	Yes Who	
Septic/Holding Tank #2	☐ Yes ☐ No	Yes No	☐ Yes ☐No	
Pretreatment Tank	Yes No	Yes No	☐ Yes ☐ No	
Pump Tank	Yes No	☐ Yes ĈNo	Yes A No	
i. How many gallons of septage were remov	red?	\	**	
Fank #1 Tank #2 Pretreatment Tank Pump Tank				
. Other information: List any troubleshooti	ng, minor repairs cond	ucted, tank safety conce	rns, or other concerns.	
. Certification: I hereby certify as a State of N	linnesota certified SSTS	Maintainer that I personal	V conducted the work	
and made the observations, t	ir airectly supervised oti	ners in the performance of	this job.	
Maintainer's Name: Olson's Sewer Service, In	nc. Maintaine	er's Address: 17638 Lyons	Street NE, Forest Lake, MN	
Maintainer's License #: 216 Mainta	iner's Phone #: 651-464	1-2082		
Maintainer's Signature	4	Date:	33 21	
			- √2, √2, √2, √2, √2, √2, √2, √2, √2, √2,	