

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	bo completed in it			, and manifest	direct crimic
prior to por	be completed in its entirety	to constitute a v	alid maintenance p	permit. This permit	must be completed
prior to peri	forming maintenance activit	ies and remain o	n-site for the dura	tion of the maintena	nce activity.
Date of Maintenance	e: <u>5 - 26 - 21</u> Reason	for Maintenance:	Rentine		
	8929 36 m St		Property Owner's N	lame: Pichcrcl	e Dime
Municipality: W	e Elmo zip: 556	M Property Ide	entification Number	•	Quin
Maintenance Permit	No: <u>84626c1274</u> 024	Azintzinar Naws	- 11:	•	011.1
	S RECOVED DO	Maintainer Name a	nd License No. Pink	<u>(y's Environmental Se</u>	wer Service/ L1673
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank ——— in			
 □ Sludge and scum measured Do tanks need to be pumped? □ Yes □ No (if no provide measurements) 		Sludge Level in Tank in Scum Level in Tank in			
		Sludge + Scum / Liquid Level X 100			
		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	emove septage: Maintenan	oce Hole Mother (11 25% of greater
			enter authorization co	ode)	
	ecurely replaced? Yes				
o. is there evidence	of tank leakage from a sept	tic, holding, preti	reatment or pump	tank below the oper	ating depth or
evidence of dam	naged, cracked, or structura	Illy unsound main	tenance hole cove	rs? Yes No	
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
. How many gallons	of septage were removed?				
Tank #1 /20	gal Tank #2	gal Pretreatment	tank ga	I Pump Tank	gal
. Other information	: List any troubleshooting,	minor repairs cor	ducted tank safet	V concerns or other	gat
System to	o old he ma	1464	and the sure	y concerns, or other	concerns.
. Location of septage	e disposal: $5t - 7$	Darl			
	Pinky's	Environmental Se	wer Service Inc		
	Pinky's	Environmental Se			

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001 P: 651-439-4847 License Number: L1673