## Washington County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in it.					
This section must be completed in its entirety	to constitute a va	lid maintenance	permit. This permit	must be complete	
prior to performing maintenance activi	ties and remain or	-site for the dura	tion of the maintena	nce activity.	
Date of Maintenance: 3 - 21 - 21 Reason	for Maintenance:	Zoutine			
Property Address: 12575 Cockrice	ge An Lo	Property Owner's	Name: Tome J	Mre Vaith	
Municipality: Stillwater zip: 550	Property Ide	ntification Number			
Maintenance Permit No. W 31(7:77)	Troperty Ide	ntineation Number			
Maintenance Permit No: <u>M3162; 22181</u>	Maintainer Name a	nd License No. Pin	ky's Environmental Se	wer Service/ L1673	
Maintenance Performed	Tank Meas	urement (must b	o complete d if to 1		
			e completed if tanks	NOT pumped)	
rank(b) ramped	Liquid Level of Tank — in				
Sludge and scum measured Do tanks need to be pumped?	Sludge Level in Tank in Scum Level in Tank in				
		Sludge + Scum / Liquid Level X 100			
Yes No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to remove septage: $\square$ Maintena	nce Hole Other (e	nter authorization c	ode)		
2. Were all covers securely replaced? Yes	\ \	ower 951			
<ol><li>Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structure</li></ol>	ally unsound maint	conspose halo sever	tank below the oper	ating depth or	
	any unsound mann	enance note cove	ers: 🗆 Yes 🗷 No		
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ♠No		
Septic/Holding Tank #2	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed?					
Tank #1 Occ gal Tank #2 occ	gal Pretreatment	tank as	A. Dissan Tauli		
5. Other information: List any troubleshooting,	minor repairs con	dusted to be s	at Pump Tank	gal	
, a canada a sa	millor repairs com	ducted, tank safe	ty concerns, or other	concerns.	
5. Location of septage disposal: St. Pau	1				
respondential of septage disposal.					
Pinky's	Environmental Sev				
	PO Box 354				

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001 P: 651-439-4847 License Number: L1673