## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT w7617220951

Date of Maintenance 10/2/20 Rea	ason for Maintenance:	_	00/01/22095/	
Property Address: 2 401 Parts	sh Road Pro	perty Owner's Name:	Suns Ole	
Municipality: Scandia	State Zip Co		Jumile Ulson	
What was done to the system?			EO Code/Property I.D. #:	
Tank(s) Pumped	Tank M	Tank Measurements (must be completed if tanks NOT pumped)		
Sludge and scum measured.	Liquid Level of Ta	in. Scum Level in.		
Do tanks need to be pumped?  Yes No (If no provide measure)	ments) Total (Sludge + S			
1. Access used to remove septage: Main	ntenance Hole CiOthor	(Co to #2 !- !- )		
2. If maintenance hole was used, were all co	Were socured and a set of the	(Go to #3 below)	<ul> <li>* Tank must be pumped if th is greater than 25%.</li> </ul>	is <b>val</b> ue
2. If maintenance hole was used, were all co- Explanation:	vers securely replaced?	Yes No please	explain	
3. If owner refuses to allow a Subsurface S them complete and sign the following s	ewage Treatment System	n (SSTS) to be pumpe	ed through the maintenance hate	
1				
hole. I understand that removal of solids a	nd liquids through only one	allow the removal of s	olids and liquids through the mainte	nance
4. Is the tank designed as a leaky tank? examp	ria ildanas tillonati Otubi s	CCACC Dainte is man an-	nsidered maintenance.	
Tank#1 T: Yes T.No Verificatio Metho	od Used: Pragad	ywell, leaching pit		
Tank#2 Yes No Verificatio Metho		1701		
5. Is there evidence of tank leakage from a	contic holding	ment or pump tank h	elou the energy	
	nd maintenance hole cov	ers?	relow the operating depth or evide	nce of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes ANO	Yes No	Yes TNo	
Septic/Holding Tank #2	Yes No	「Yes 「No	☐ Yes ☐ No	
Pretreatment Tank	Yes No	Yes No	☐ Yes ☐ No	
Pump Tank	Yes No	Yes No	☐ Yes ☐ No	
6. How many gallons of septage were remov	red?	to a constant	1163  140	
Tank #1 / 100 Tank #2	Pretreatment Tan	,	Pump Tank	
7. Other information: List any troubleshootii	ng, minor repairs conduc	ted, tank safety cond	erns, or other concerns.	
<b>S. Certification:</b> I hereby certify as a State of M and made the observations, o	linnesota certified SSTS Ma r directly supervised other	nintainer that I person	ally conducted the work	
Maintainer's Name: 0551	Maintainer's		& Lyns St. N	c
Maintainer's License #: Maintai	ner's Phone #: 444-2	7083	-4 w st. 14	
Maintainer's Signature			0-2-20	