

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

nuiou to	be completed in its entire	ty to constitute a va	alid maintenance	permit. This permit	must be complete	
prior to per	forming maintenance activ	rities and remain or	-site for the dura	ition of the mainten	ance activity	
Date of Maintenance	e: Reason	on for Maintenance:	Bontine			
Property Address: 2	470 Oriole Ave	n	Property Owner's	Name: Roger and	Yerasa Mathieu	
Municipality: Sti	11 waxa ZIP: 55	Property Ide	ntification Numbe	r:		
Maintenance Permit	No: <u>V 3088 L 22708</u>	Maintainer Name a	ad Liconco No. Din	lud- E		
		The state of the state of	id License No. Pill	ky s Environmental S	ewer Service/ L167	
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
☐ Sludge and scum measured			Sludge Level in Tank ——— in Country in Country			
Do tanks need to be pumped? Yes No (if no provide measurements)		Sludge + Scum	The state of the s			
		s) = % Sludge & Sci		anks must be pumped		
1. Access used to re	emove septage: Mainten	ance Hole DOther (c			20% of greater	
	securely replaced? Yes		mer authorization c	ode)		
Is there evidence	e of tank leakage from a se naged, cracked, or structu	ptic, holding, pretr	eatment or pump tenance hole cove	tank below the ope ers? Yes No	rating depth or	
	- 1					
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	Leaking Out Yes No	Leaking In Yes No	Cover Damage Ves No		
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No		
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☑ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☑ No ☐ Yes ☑ No ☐ Yes ☐ No		
4. How many gallons Tank #1 <u>l</u> oco	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank Sof septage were removed	☐ Yes ☑ No ☐ Yes ☑ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		
Tank #1 1000	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank s of septage were removed gal Tank #2	Yes No Yes No Yes No Yes No Yes No gal Pretreatment	Yes No Yes No Yes No Yes No Yes No	Yes No Yes No Yes No Yes No	gal	
Tank #1 1000	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank Sof septage were removed	Yes No Yes No Yes No Yes No Yes No gal Pretreatment	Yes No Yes No Yes No Yes No Yes No	Yes No Yes No Yes No Yes No	gal er concerns.	
Tank #1 1000	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank s of septage were removed gal Tank #2	Yes No Yes No Yes No Yes No Yes No gal Pretreatment	Yes No Yes No Yes No Yes No Yes No	Yes No Yes No Yes No Yes No	gal er concerns.	
Tank #1 <u>loco</u> 5. Other information	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank s of septage were removed gal Tank #2	Yes No Yes No Yes No Yes No Yes No gal Pretreatment minor repairs con	Yes No Yes No Yes No Yes No Yes No	Yes No Yes No Yes No Yes No	gal er concerns.	
Tank #1 <u>loco</u> 5. Other information	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank s of septage were removed gal Tank #2	Yes No Yes No Yes No Yes No Yes No gal Pretreatment minor repairs con	Yes No Yes No Yes No Yes No Yes No	Yes No Yes No Yes No Yes No	gal er concerns.	
Tank #1 <u>loco</u> 5. Other information	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank s of septage were removed gal Tank #2 Locc n: List any troubleshooting e disposal:	Yes No Yes No Yes No Yes No Yes No Regal Pretreatment Regal pretreatment Regal Pretreatment	Yes No Yes No Yes No Yes No Yes No tank gaducted, tank safe	Yes No Yes No Yes No Yes No	gal er concerns.	
Tank #1 <u>loco</u> 5. Other information	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank s of septage were removed gal Tank #2 Locc n: List any troubleshooting e disposal:	Yes No Yes No Yes No Yes No Yes No gal Pretreatment minor repairs con	Yes No Yes No Yes No Yes No Yes No tank gaducted, tank safe	Yes No Yes No Yes No Yes No	gal er concerns.	

Afton MN 55001

P: 651-439-4847 License Number: L1673