

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be considered to				idice reilli	
This section must be completed in its en	cirety to constitute a v	alid maintenance	permit. This permit	must be complet	
prior to performing maintenance a	ctivities and remain o	n-site for the dura	tion of the maintena	nce activity.	
Date of Maintenance: 5-19-21 R	eason for Maintenance:	Boutine			
Property Address: 13343 Otchip	we Aven	Property Owner's	Name Ponny +	told 1.	
Municipality: Styllways ZIP:	Property Ide	entification Numbe	r:	OTTOVICE	
Maintenance Permit No: X 05172227	Maintainer Name a	and License No. Pin	kv's Environmental So	wor Coming / 146	
			sy 5 Environmental Se	wer service/ L16	
Maintenance Performed	Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
☐ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measureme		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: $\Box$ Mair	stenance Hole When			11 25% of greater	
3. Is there evidence of tank leakage from a evidence of damaged, cracked, or stru  ———————————————————————————————————	a septic, holding, pretocturally unsound main  Leaking Out	reatment or pump tenance hole cove Leaking In	tank below the operers? Yes No	ating depth or	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were remo					
Tank #1 /200 gal Tank #2	gal Pretreatment	tank ga	l Pump Tank	anl	
. Other information: List any troubleshoot	ing, minor repairs cor	ducted, tank safe	v concerns or other	gat	
manhale under landscaping.	Cannot Expor	د	y concerns, or other	concerns.	
				1142	
. Location of septage disposal: 54.	Da-/			s. Iu	
,				1 11 11 11	
Pi	nky's Environmental Se	wer Service Inc.			
	PO Box 35	1			
	Afton MN 550	001		To the	

Maintenance activities must be reported to the Department within 90 days.

P: 651-439-4847 License Number: L1673