

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	e completed in its entirety orming maintenance activit	to constitute a valid maintena ies and remain on-site for the	ance permit. This permit	nust be completed
Date of Maintenance	: 5-17-21 Reason	for Maintenance: Ruhu		ice activity.
Property Address:	385 Quinton Are	So Property Own	ner's Name: Brion 1	assica Have
Municipality: (WC	lenel zip:550	Property Identification No	umber:	
		Maintainer Name and License No		wer Service/ L1673
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)		
Tank(s) Pumped		Liquid Level of Tank — in		
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in		
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100		
Yes No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater		
1. Access used to re	move septage: Maintenan	ce Hole Other (enter authoriza		
evidence of dam	aged, cracked, or structura Tank	lly unsound maintenance hole Leaking Out Leaking Ir	e covers? Yes No	ating depth of
	Septic/Holding Tank #1	☐ Yes ☑ No ☐ Yes ☑	No 🗆 Yes 🗖 No	
	Septic/Holding Tank #2	☐ Yes ☐ No ☐ Yes ☐	No ☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No ☐ Yes ☐	No ☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No ☐ Yes ☐	No ☐ Yes ☐ No	
Tank #1 (2.5c)	of septage were removed?	gal Pretreatment tank		
. Other information	: List any troubleshooting.	minor repairs conducted, tank	gal Pump Tank	gal
		- Famo Goriadotad, tarih	safety concerns, or other	concerns.
. Location of septage	e disposal: St gan1			
	Pinky's	Environmental Sewer Service Ir	nc.	
		PO Box 354		
		Afton MN 55001		

Maintenance activities must be reported to the Department within 90 days.

P: 651-439-4847 License Number: L1673