Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must	t be completed in its entiret	y to constitute a v	alid maintenance	permit. This permit	must be complete	
<u>prior</u> to pe	erforming maintenance activ	rities and remain o	n-site for the dura	ation of the maintena	ance activity	
Date of Maintenan	ce: <u>5-14-21</u> Reason	n for Maintenance:	Routine		mod decivity.	
Property Address:	206 East Low	st St	Property Owner's	Name: Dayy.	nnes	
Municipality: St	illwater zip: 5 ;	V8> Property Ide	entification Numbe	r:		
Maintenance Perm	it No:91385222780	Maintainer Name	and License No. Die	Inda Foot		
J.		Traine t	and License No. Pill	ky s Environmental Se	ewer Service/ L167	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank ——— in			
☐ Sludge and scum measured			Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)			= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to	remove septage: Maintena	ance Hole Tother (ontor outhorization		11 25% of greater	
	securely replaced? Yes		enter authorization c	ode)		
evidence of da	ce of tank leakage from a se	ptic, holding, pret	reatment or pump	tank below the oper	ating depth or	
	maged, cracked, or structur	ally unsound main	tenance hole cove	ers? Yes No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallor	ns of septage were removed	?				
Tank #1 /300	gal Tank #2	_gal Pretreatment	tankga	al Pump Tank	aal	
5. Other information	on: List any troubleshooting,	minor repairs cor	ducted, tank safe	ty concerns or other	gal	
545tem	two old for m	anhale	auteu, tuink suite	ty concerns, or other	concerns.	
(
6. Location of septa	ge disposal: 51. Po	ur/				
	Pinky'	s Environmental Se	wer Service Inc			
		PO Box 35				
		Afton MN 550				

Maintenance activities must be reported to the Department within 90 days.