DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

| Date of Maintenance 10-21-15 Reason | for Maintenance: | utine | | |
|---|-------------------------------|----------------------------|---|-------------|
| Property Address: 1475 NGA Fix | C.C.M. Proper | ty Owner's Name: 近 | le Peleski | |
| Municipality: <u>Lake Elmo</u> | State MN Zip Code | 55042 GEO COO | de/Property I.D. #: | |
| What was done to the system? | Tank Mea | surements (must be con | ipleted if tanks NOT pumpe | d) |
| Tank(s) Pumped Sludge and scum measured. | Liquid Level of Tan | k in. Sludge L | evel in. Scum Level | in. |
| Do tanks need to be pumped? Yes No (If no provide measureme | nts) Total (Sludge + Scu | m) / Liquid Lev | | |
| 1. Access used to remove septage: Mainte | enance Hole 🔲 Other (G | Go to #3 below) | * Tank must be pumped if is greater than 25%. | this value |
| 2. If maintenance hole was used, were all cover | | | - | |
| Explanation: | | | | |
| 3. If owner refuses to allow a Subsurface Se them complete and sign the following sta | | (SSTS) to be pumped t | hrough the maintenance ho | le, have |
| l,(| owner's name), refuse to | allow the removal of solic | ls and liquids through the ma | intenance |
| hole. I understand that removal of solids an | d liquids through other a | ccess points is not consid | ered maintenance. | |
| 4. Is the tank designed as a leaky tank? example | le: seepage pit, cesspool, di | rywell, leaching pit | | |
| Tank#1 Yes No Verificatio Metho | d Used: | | | |
| Tank#2 Yes No Verificatio Metho | od Used: | | | |
| 5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsou | septic, holding, pretreat | tment or pump tank bel | ow the operating depth or e | evidence of |
| Tank | Leaking Out | Leaking In | Cover Damage | |
| Septic/Holding Tank #1 | Yes No | Yes No | Yes No | |
| Septic/Holding Tank #2 | Yes No | Yes No | Yes No | |
| Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| Pump Tank | Yes No | Yes No | Yes No | |
| 6. How many gallons of septage were remo | ved? | | | |
| Tank#1 1500 Tank#2 1000 | Pretreatment Ta | ank P | ump Tank | |
| 7. Other information: List any troubleshoo | ting, minor repairs cond | ucted, tank safety conc | erns, or other concerns. | |
| 8. Certification: I hereby certify as a State of and made the observations | , or directly supervised ot | hers in the performance o | of this job. | |
| Maintainer's Name: PINKY'S SEWER SERVIC | E Maintain | er's Address: P.O. Box 354 | 4 Afton, MN 55001 | |
| Maintainer's License #: 1673 Main | tainer's Phone #: 651-43 | | | |
| Maintainer's Signature | 11-1 | Date: 10 | - 1 -(') | |