

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed

Date of Maintenance:	3-24-21 Peacen 6	or Maintenance:		ion of the maintena	nce activity.
Property Address: 71	560 Novak A	or Maintenance:	protest.	Chals To	11/20
Property Address: 21	1.	2	roperty Owner's N	ame:	Yor
Municipality:	1560 Novak Ace Ven ZIP: 5507	Property Ide	ntification Number:		
Maintenance Permit No	:p5271K21761M2	aintainer Name a	nd License No. Smil	ie's Sewer Service/L	2428
	•				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped Sludge and scum measured		Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	ove septage:  Maintenand	ce Hole Other (	enter authorization co	ode)	
2. Were all covers sec	urely replaced? Yes	√ No			
			eatment or nump	tank below the one	rating depth or
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?   Yes No					
ſ					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🌣 No	☐ Yes ☒ No	☐ Yes ဩNo	
	Septic/Holding Tank #2	☐ Yes ☒No	☐ Yes ☒No	☐ Yes 🖄 No	
	Pretreatment Tank	$\square$ Yes $\square$ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of	of septage were removed?				
Tank #1_1000	gal Tank #2	gal Pretreatmen	t tank ga	al Pump Tank	gal
Tank #1 1000 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank gal 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
		1-000			
6. Location of septage	disposal:	Actro			
					ACCORDANGE OF THE SECOND SECON

Smilie's Sewer Service **PO BOX 100** Scandia, MN 55073 License# 2428 P: 651-433-3934

Maintenance activities must be reported to the Department within 90 days.