## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT m 8902b23279

Date of Maintenance 6-29-21 Reas	son for Maintenance:			
Property Address: 22366 Kick	Ct North Pro	operty Owner's Name:	Bryan Gaffy	
Municipality: Scandia	State MN Zip Co	ode 55073 GEO	Code/Property I.D. #:	
What yas to be contraspond a	¥ # Perest rance/	សមាលាស្រីកម្រាល់ស្រី	ompleted franki No epumpe	6) 1 125
Tank(s) Pumped	Liquid Level of T	ank in Chada	e Level in. Scum Level	4410
Sludge and scum measured.  Do tanks need to be pumped?	Liquid Level Of 1	ank in. Sludge	e Level in. Scum Level	in. ——
Yes No (If no provide measuren	Total (Sludge + S	icum) / Liquid L	evel = % Sludge & Scul	n
1. Access used to remove septage: Mair		//Go to #2 holow\	* Tank must be pumped if t	his value
2. If maintenance hole was used, were all cov			is greater than 25%.	
	reis securely replaced?	X yes   No please exp	olain	
Explanation:				
3. If owner refuses to allow a Subsurface Statem complete and sign the following st	ewage Treatment Syste atement:	m (SSTS) to be pumped	through the maintenance hole	, have
I,	(OWner's name) refuse to	allow the removal of col	ids and liquids through the main	
hole. I understand that removal of solids a	nd liquids through other	access points is not consi	dered maintenance dered maintenance	tenance
4. Is the tank designed as a leaky tank? examp			ocica mantenance.	
Tank#1 Yes No Verificatio Metho		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
To Line Verificatio Metri				
Tank#2 Yes No Verificatio Metho				
<ol><li>is there evidence of tank leakage from a damaged, cracked, or structurally unsou</li></ol>	septic, holding, pretrea	tment or pump tank be	low the operating depth or evi	lence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	Ti Yes X No	Yes No	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	☐ Yes ☐ No	
Pump Tank	Yes No	Yes No	Yes No	
5. How many gallons of septage were remo	ved?			
Tank #1 1000 Tank #2 1000	Pretreatment Ta	nk Pu	ımp Tank	
7. Other information: List any troubleshoot	ing, minor repairs cond	ucted, tank safety conce	erns, or other concerns.	
B. Certification: I hereby certify as a State of I and made the observations,	Minnesota certified SSTS or directly supervised other	Maintainer that I personal ners in the performance o	lly conducted the work	
Maintainer's Name: Olson's Sewer Service,			Street NE, Forest Lake, MN	
Maintainer's License #: 216 Mainta	ainer's Phone #: 651-46	1-2082		
Maintainer's Signature	70 SS	Date:	-29-21	