

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

71.					
This section must be completed in its entirety	to constitute a	alid maintenance p	permit. This permit	must be complet	
<u>prior</u> to performing maintenance activit	ies and remain o	n-site for the dura	tion of the maintana	nes setivity	
Date of Maintenance: 5-10-2/ Reason	for Maintenance:	CZU	tion of the maintena	nce activity.	
Property Address: 11480 Leasing	AUPN	Property Owner's N	lame: (4) Por	teccho	
Municipality: Sti Nuiter ZIP:	Droposti, Id			473073	
250210 20011	Property Id	entification Number	:		
Maintenance Permit No: DS924h22414N	Maintainer Name	and License No. Pink	y's Environmental Se	wer Service/ I 16	
				The second secon	
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped	Liquid Level of Tank — in				
☐ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
$\square$ Yes $\square$ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
1 Access used to remove contents			iks must be pumped	25% or greater	
1. Access used to remove septage:   Maintenan		enter authorization co	ode) TODOIC		
2. Were all covers securely replaced? $\Box$ Yes $\Box$					
3. Is there evidence of tank leakage from a sept	ic, holding, pret	reatment or pump	tank below the oper	ating donth or	
evidence of damaged, cracked, or structura	lly unsound mair	tenance hole cove	rs?  Yes  No	acing depth of	
Tank					
	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
I. How many gallons of septage were removed?					
Tank #1 / O B gal Tank #2	pal Pretreatment	tank			
Other information: List any troubleshooting, r	ninor ronaire es	dust dust dust ga	Pump Tank	gal	
and any arountedinocting, i	illior repairs cor	iducted, tank safet	y concerns, or other	concerns.	
. Location of septage disposal:				1	
Location of septage disposat:					
Pinky's I	Environmental Se	wer Service Inc			

PO Box 354

Afton MN 55001